Submit 3 Copies	State of New Mexico		Form C-103
o Appropriate	Energy, Minerals, and Natural Resources Department		Revised 1-1-89
District Office			
DISTRICT I	OIL CONSERVATION DIVISION		WELL API NO.
2.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		30-059-20089
DISTRICT II 2.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE FEE
DISTRICT III			6. State Oil & Gas Lease No.
000 Rio Brazos Rd., Aztec, NM 87410			or state on & das pease 110.
SHND	V NOTICES AND DEPORTS	ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)			
Type of Well			BRAVO DOME CO2 GAS UNIT
	GAS WELL OTHER	CO2	
1. Name of Operator			8. Well No.
AMOCO PRODUCTION COMPANY			1935-131F
. Address of Operator			9. Pool name or Wildcat
P.O. Box 303, AMIS	TAD, NEW MEXICO 88410		BRAVO DOME CO2 GAS UNIT
	TAB, NEW MEXICO COTTO		DIVIVO BOINE CO2 GAO GIVIT
Well Location Unit Letter F :	1980 Feet From The Nor	th Line and 1980	Feet From The West Line
	Township 19N		
Section 13	· · · · · · · · · · · · · · · · · · ·		PM Union County
	10. Elevation (She	ow whether DF, RKB, RT, GR, etc.) 4497 GR	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING			
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS	S. PLUG AND ABANDONMENT
ULL OR ALTER CASING		CASING TEST AND CEMENT	JOB
LJ			<u></u>
THER		OTHER.	
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
MIRUSU, kill well as necessary, NUBOP, release packer, lay down production tubing and packer, run workstring to 2,194			
feet, spot 53 sacks of class C cement, pull workstring, WOC, run workstring, tag cement, cement should be above 2,019			
feet, pressure test casing to 500 psi, displace casing with corrosion inhibited fluid, pull workstring to 1,601 feet, spot 12			
sacks of cement, pull workstring to 30 feet and fill casing with cement, NDBOP, RDMOSU, cut off wellhead, install PXA			
marker, cut off well anchors and clean location.			
\sim \sim \sim \sim \sim	we is true and complete to the best of my kr	_	
GNATURE MATURE	Combo TITL	E Field Foreman	DATE 2-29-00
YPE OR PRINT NAME Danny J. H	olcomb		TELEPHONE NO. (505) 374-3010
This space for State Usey	A Star TITL	E DISTRICT SUPERV	1500 DATE 3/9/00
ONDITIONS OF APPROVAL, IF ANY	John TITL	L. AND SERVICE OF THE PROPERTY	- J/7/W
ONUTIONS OF AFFROVAL, IF AIM.	<i>'</i>		