Submit 3 Copies to Appropriate	State of New Mexico Energy, Minerals, and Natural Resources Department		Form C-103 Revised 1-1-89	
District Office	OIL CONCEDUATION	DIVICION	WELL ADING	
DISTRICT I	OIL CONSERVATION DIVISION		WELL API NO.	
P O Box 1980, Hobbs, NM 88240	P.O. Box 2088		30-050-20109	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 8750	4-2088	5. Indicate Type of Leas	se FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Leas	e No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
Type of Well ON WELL ON WELL	1 1		BRAVO DOME CO2 GAS UN	IT
2. Name of Operator			8. Well No.	
AMOCO PRODUCTION COMPANY			2035-17 1K	
3 Address of Operator			9. Pool name or Wildcat	
P.O. Box 303, AMISTAD,	NEW MEXICO 88410		BRAVO DOME CO2 GAS UN	IT
4. Well Location Unit Letter K: 1930 Feet From The SOUTH Line and 1980 Feet From The WEST Line				
Section 17	Township 20N Rang	ge <u>35E</u> NMI	PM UNION	County
	10. Elevation (Show whether I	DF, RKB, RT, GR, etc.)		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND	ABANDONMENT
TEMPORARILY ABANDON	CHARGE FEATS			ADATO STRICT
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB		
OTHER:		OTHER:		<u> </u>
12. Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
down production tubing, p Cap CIBP with 50 feet of o brine water. Pull tubing to tubing to a depth plus or n surface casing for pressur	well as necessary with fresh water. I acker, tailpipe. Run and set with with element. Run 2-3/8" tubing to just about 1790'. Pump 12 sacks cement. Dininus 30 feet. Fill top of casing with e. Cut off surface casing head. We sell panels. Cut service unit anchors	reline a CIBP @ 2218 bove cement cap on CI splace cement from tu cement. Pull final join eld steel plate on top of	b. Pressure test casing BP. Displace casing bing with 9.5# gelled but of tubing from the wife casing and install PX	g to 500 psi. with 9.5# gelled orine water. Pull ell. Check
Thereby certify that the information above is true and SIGNATURE TYPE OR PRINT NAME B. E. Prichage	d complete to the best of any knowledge and belief.	ations Specialist	DATE 10/2 TELEPHONE NO.	7:97 (505) 374-3053
(This spece for State Use)	Ush		- //	1/17/97
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	nnenne		DATE	111/1/