ubmit 3 Copies	State of New Mexico			Form C-103	
Appropriate	Energy, Minerals, and Natural Resources Department		Revised 1-1-89		
istrict Office	OH CONCEDUATIO	N DIVISION	WELLADING		
PISTRICT I	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-059-20130		
.O. Box 1980, Hobbs, NM 88240	Santa Fe, New Mexico 87504-2088				
Santa Fe, New Mexico 8/304-2008  Drawer DD, Artesia, NM 88210		5. Indicate Type of Lease STATE FEE FEE			
NISTRICT III 100 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease	No.	
<del>-</del>	NOTICES AND REPORTS ON W				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name		
(FORM C-101) FOR SUCH PROPOSALS.)					
Type of Well			BRAVO DOME CO2 G	AS UNIT	
OIL GA WELL WE	S OTHER	CO2			
Name of Operator			8. Well No.		
AMOCO PRODUCTION COMPANY			2433-351G		
Address of Operator 9. P			. Pool name or Wildcat		
P.O. Box 303, AMISTAD, NEW MEXICO 88410 BRA			BRAVO DOME CO2 G	AVO DOME CO2 GAS UNIT	
Well Location					
Unit Letter G : 19		Line and 1980		East Line	
Section 35	<del></del>	Range 33E NMP	M Union	County	
	10. Elevation (Show whet	her DF, RKB_RT, GR, etc.; GR	•		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
ERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK			ALTERING	CASING	
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS			PLUG ANI	D ABANDONMENT	
				71.3711120111112111	
JLL OR ALTER CASING					
THER:		OTHER.			
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103.					
MIRUSU, kill well as necessary, NUBOP, release packer, lay down production tubing and packer, run cast iron bridge plug with wireline, set CIBP at 2,492 feet, run workstring, displace casing with mud laden fluid, pressure test casing to 500 psi,					
cap CIBP with 5 sacks of cement, pull workstring to 2,111 feet, spot 9 sacks of cement, pull workstring to 30 feet, fill casing					
with cement, NDBOP, cut off wellhead, install PXA marker, RDMOSU, cut off well anchors and clean location.					
nereby certify that the information above	is true and complete to the best of my knowledge	ge and belief			
SNATURE / / / /	Comb TITLE	Field Foreman	DATE 8-18-	99	
PE OR PRINT NAME Panny J. Holco			TELEPHONE NO	(505) 374-3010	
his space for State Use)	John TITLE D	ACTUAL SOLETION	DATE 8/2	23/99	
ONDITIONS OF APPROVAL IF ANY					