Submit 3 Copies	State of New M		Form C-103
to Appropriate	Energy, Minerals, and Natural Resources Department		Revised 1-1-89
District Office	OF COMORDIATIO	ANT TARTECT CORE	
DISTRICT I	OIL CONSERVATION DIVISION		WELL API NO.
P.O. Box 1980, Hobbs, NM, 88240	P.O. Box 20		30-059-20159
DISTRICT II P.O. Drawer DD, Artesia, NM, 88210	Santa Fe, New Mexico 8	7504-2088	5. Indicate Type of Lease  STATE FEE FEE
<u>DISTRICT III</u>			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87416			
1	OTICES AND REPORTS ON W		
	PROPOSALS TO DRILL OR TO DEEPEN OR SERVOIR. USE "APPLICATION FOR PERMIT		7. Lease Name or Unit Agreement Name
	RM C-101) FOR SUCH PROPOSALS :		7. Bease Name of Clift Agreement Name
1. Type of Well			BRAVO DOME CO2 GAS UNIT
O'L GAS WELL WELL	OTHER	CO2	
2. Name of Operator			8. Well No.
AMOCO PRODUCTION CO	DMPANY		2431-361M
3. Address of Operator		<del>- 4 - 5 - 4 </del>	9. Pool name or Wildcat
P.O. Box 303, AMISTAD	, NEW MEXICO 88410		BRAVO DOME CO2 GAS UNIT
4. Well Location			
Unit Letter M : 990 Feet From The South Line and 100 Feet From The West Line			
Section 36	Township 24N	Range 31E NMI	PM Union County
	10. Elevation /Show whe 5597	ther DF, RKB, RT, GR, etc.) GR	
NOTICE OF IN	TENTION TO:	SUBSE	EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT.	<b>ЈОВ</b>
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations	(Clearly state all pertinent detail)	s and give pertinent dates including a	estimated data of starting any proposed work)
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103.			
MIRUSU, kill well as necessary, NUBOP, release packer, lay down production tubing and packer, run cast iron bridge plug with wireline, set CIBP at 2,359 feet, run workstring, displace casing with corrosion inhibited fluid, pressure test casing to 500 psi, cap CIBP with 5 sacks of class C cement, pull workstring to 2,000 feet, spot 13 sacks of cement, pull workstring to 30 feet, fill casing with cement, NDBOP, RDMOSU, cut off wellhead, install PXA marker, cut off well anchors and clean location.			
I hereby certify that the information above is t	- D	ge and belief Field Foreman	DATE 3-6-00
		rieid rotettian	DATE 3-6-00
TYPE OR PRINT NAME Danny & Holcom	dib /		TELEPHONE NO (505) 374-3010
(This space for State Use)  APPROVED BY  CONDITIONS OF APPROVAL, IF ANY:	When TITLE D	ISTRICT SUPERV	ISOR DATE 3/10/00