

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised August 8, 2011
 Submit 1 Copy to appropriate District Office in
 accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company	Linn Operating Inc.	Contact	E.L. Gonzales
Address	2130 W Bender Blvd Hobbs, NM 88240	Telephone No.	575-738-1739
Facility Name	Caprock Maljamar Unit # 152	Facility Type	Oil producer
Surface Owner	State	Mineral Owner	
		API No.	30-025-32042

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	17	17S	33E	1355	South	1351	West	Lea

Latitude 32.8310476393633 Longitude -103.689563211149

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	30 bbls	Volume Recovered	25 bbls
Source of Release	Stuffing box	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jeff Robertson - BLM / Mike Bratcher- NM OCD / Tomas Oberding-OCD		
By Whom?	Brian Wall / Theresa McCracken	Date and Hour	08/25/2014 0700 / 08/26/2014 0958		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* As I was checking wells I pulled up to CMU 152, and realized the stuffing box was leaking, The well had a trapper on it, but water was running out of it and didn't shut well off. First thing I did was shut well in and got leak to stop, Then I notified my foreman. I got a vacuum truck to pick up water off of ground, he picked up 25bbls of produced water.

Describe Area Affected and Cleanup Action Taken.* The area affected was to the south app. 25' long and 4' wide, and to the north it ran 35" long and was 3' wide. While I had the vacuum truck I changed the packing & greased well, then returned well to production.

Directions to site: Turn on dog lake road north off of 529, go 6/10 mile to stop sign, turn right onto mescalero rd, go to top of cap, turn left onto hummingbird rd, go 6miles to tomahawk rd, turn left onto tomahawk rd, follow tomahawk to y in rd, stay right on y go till you come to injection plant. Continue north till you come to a 3 way, continue north and cmu 152 1st well on right.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: E.L. Gonzales	Approved by Environmental Specialist: 	
Title: Production Supervisor	Approval Date: 03/06/2015	Expiration Date: //
E-mail Address: elgonzales@linenergy.com	Conditions of Approval: //	Attached <input type="checkbox"/>
Date: 03/05/2015 Phone: 505-504-8002		IRP-3275

* Attach Additional Sheets If Necessary