

From: Eric_Maestas@oxy.com
To: [Bayliss, Randolph, EMNRD](#)
Subject: FW: OXY Bravo Dome Spill
Date: Thursday, March 9, 2017 1:29:14 PM
Attachments: [Oxy USA INC.docx](#)

From: Maestas, Eric H
Sent: Thursday, March 09, 2017 1:10 PM
To: 'Randy.Bayliss@state.nm.us' <Randy.Bayliss@state.nm.us>
Cc: Summers, Casey L <Casey_Summers@oxy.com>
Subject: OXY Bravo Dome Spill

Mr. Bayliss,

The attached document and information below is for the Leg 10 well #1932-331G
Produced water spill that was turned in 3-8-2017.

GPS – Lat. N35.836 Long. W-103.54108
Location – Unit G, Section 33, Township 19, Range 32
API – 30-021-20376

An underground valve had been opened by the livestock in the area which allowed
for Produced Water and CO2 to mist onto the ground from a Drip location on a CO2
flowline. We have installed an above ground 2” ball valve and have plugged the valve
to prevent reoccurrence.

Thank you,

Eric Maestas
HES Ops Coordinator
Bravo Dome Sheep Mountain
cell: (575)420-7825