

4441 District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company	Contact Rebecca Jamison, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-5538
Facility Name Ichabod 7 Federal 1H	Facility Type Oil
Surface Owner Federal	Mineral Owner Federal
API No 30-025-40043	

LOCATION OF RELEASE

Unit Letter P	Section 7	Township 26S	Range 34E	Feet from the 195	North/South Line South	Feet from the 330	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude: 32.0511932

Longitude: -103.5014954

NATURE OF RELEASE

Type of Release Oil	Volume of Release 33BBLS	Volume Recovered 33BBLS
Source of Release Oil Storage tank	Date and Hour of Occurrence 8/10/2017 @ 5:30 PM	Date and Hour of Discovery 8/10/2017 @ 5:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Olivia Yu BLM-Shelly Tucker	
By Whom? Rebecca Jamison, Production Foreman	Date and Hour BLM-8/10/2017 @ 8:39 AM OCD-8/10/2017 @ 9:38 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	


If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Oil storage tanks overflowed into the lined SPCC containment.

Describe Area Affected and Cleanup Action Taken.*

Approximately 33BBLS of oil was released as a result of a hole in the bottom of the oil storage tank. A vacuum truck was dispatched and approximately 33BBLS oil was recovered. All fluids remained inside the lined SPCC containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Dana DeLaRosa	OIL CONSERVATION DIVISION	
Printed Name: Dana DeLaRosa	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 8/28/2017	Expiration Date:
E-mail Address: dana.delarosa@dmv.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Phone: 575.746.5594	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1724031524