

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Chevron Midcontinent LP	Contact	Larry Ridenour
Address	HCR 60 Box 423 Lovington, NM 88260	Telephone No	(505) 396-4414 x 102
Facility Name	Lovington Paddock #7	Facility Type	Injection Line
Surface Owner:	City of Lovington	Mineral Owner:	State of NM
		Lease No.	9077-2
		IRP #	1604
		API #	30-025-03747

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	25	16S	36E	330	South	330	East	Lea

Latitude N 32 deg. 53 min. 12.85 sec. Longitude W 103 deg. 18 min. 1.02 sec.

NATURE OF RELEASE

Type of Release ¹	Produced Water	Volume of Release	20 BW	Volume Recovered	15 bbl fluids
Source of Release	Injection line	Date and Hour of Occurrence	9/26/07 7:15 AM	Date and Hour of Discovery	9/26/07 7:30 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Pat Caperton		
By Whom?	Larry Ridenour	Date and Hour	9/27/07 10:25 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Fiberglass line parted in collar. Leak detected by SCADA system and was shut in very shortly thereafter. Roustabout gang was dispatched with enviro vat to pick up standing water. Picked up 15 bbls of water total. Estimate total spill at 20 bbls water with skim of oil. Emergency one call was done and contaminated dirt removal began on 9/27/07 Chlorides: 35,300

Describe Area Affected and Cleanup Action Taken.*

An area approximately 100' x 80' was excavated to a depth of one to two feet bgs. Soil borings were installed in order to assess the horizontal and vertical limits of the spill. Additional soil was excavated at the center and northeast portions of the site until confirmation samples reported all chloride and TPH concentrations below the New Mexico clean up standards. Impacted soil was hauled to an NMOCD approved disposal facility, and the area was backfilled with clean soil from the State of New Mexico pit #294.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Larry Ridenour	Approved by District Supervisor: 	
Title: Operations Representative	Approval Date: 1/30/08	Expiration Date: 1/30/08
E-mail Address: Lridenour@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/24/08	Phone: (505) 396-4414 x 102	

* Attach Additional Sheets If Necessary