

OIL CONSERVATION COMMISSION

P. O. BOX 871

SANTA FE, NEW MEXICO

March 11, 1954

Mrs. Libby Connor
Iceco, Incorporated
115 West Center St.
Tucumcari, New Mexico

Re: Libby #1 SWNE Sec. 31-T 20 N, R 31 E
Libby #2 SWNW Sec. 32-T 20 N, R 31 E
DeBaca #2SWNE Sec. 31-T 20 N, R 31 E
HARDING COUNTY

Dear Mrs. Connor:

We have your letter of March 4 wherein you request information and logs on the above captioned wells. Although our files on these wells are somewhat lacking in such pertinent data I shall endeavor to comply.

Please find enclosed a copy of the log on the Libby #1 well and also some data on the record. This was all submitted to this office on Nov. 19, 1951 by Mr. Frank C. Holden on Form C-105. Also enclosed is a copy of the log on the American Producers Corp. No. 1 well which we assume to be the Libby #2 as it has the same quarter-quarter and section as the latter. This is on file as the State Bureau of Mines & Mineral Resources well log #1259.

The DeBaca #2 well was originally drilled by the Colo-Mex Gas Company, thence transferred to Iceco, Inc. on Dec. 3, 1949. Iceco, finding the 6" casing in this well deteriorated and the hole full of water, in turn ran a string of 5 3/16" casing to a depth of 1989' and cemented same with 294 sacks. This work was done during the interim 11-28-49 to 1-18-50 and the cementing was by Halliburton. Following this the well came in making CO₂ gas at its usual pressure, dry of water and without any surface leaks.

A report on repairs made to the Libby #2 well submitted by Mr. Frank C. Holden and dated Jan. 7, 1952 reflects the following:—"The dates of this work were as follows: 2-5-52. Notice of intention to do the work was not submitted on Form C-102 and approval of the proposed plan was not obtained. DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED: A leak of low pressure gas between 5 1/2" production string and 13 3/4" surface casing was noticed. Halliburton Cementing Company truck #2174 in charge of G. R. Roach was sent for and 180' of 1" tubing inserted between these pipes and 242 sacks of cement were pumped in, completely closing off this gas. Tubing left in hole and cleared in case similar trouble noticed, work can be done from outside again. Suggested by Halliburton."

CONSERVATION COMMISSION

P. O. BOX 871

QUINTA REAL, NEW MEXICO

March 19, 1954

Dear Sirs:

Enclosed for you are two copies of a report on the results of the first year's work of the Conservation Commission. The report is in two parts, one dealing with the general situation and the other with the specific work of the Commission.

Sincerely,
[Signature]

The report is a summary of the work of the Commission during the year 1953. It is divided into two parts, one dealing with the general situation and the other with the specific work of the Commission.

The first part of the report deals with the general situation. It discusses the progress of the Commission's work during the year and the results of its various projects. It also discusses the financial situation of the Commission and the amount of money that has been raised.

The second part of the report deals with the specific work of the Commission. It discusses the work of the various committees and the results of their work. It also discusses the work of the field stations and the results of their work.

I hope that you will find the report interesting and informative. It is a summary of the work of the Commission during the year and it shows the progress that has been made. I am sure that you will be pleased with the results of the Commission's work.