

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103 -
Revised 10-1-73

SUNDARY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		3a. Indicate Type of Lease State ☐ Fee ☐ 3. State Oil & Gas Lease No.
1. OIL WELL ☐ GAS WELL ☒ OTHER <u>C02</u>	Bravo Dome Carbon Dioxide Gas Unit	
2. Name of Operator AMOCO PRODUCTION COMPANY	Bravo Dome Carbon Dioxide Gas Unit	
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 2133-321G	
4. Location of Well UNIT LETTER <u>G</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>21-N</u> RANGE <u>33-E</u> NMPM.	Bravo Dome Carbon Dioxide Gas Unit 240-Acre Area	
15. Elevation (Show whether DF, RT, GR, etc.) 5012' GL		12. County Harding

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to reperfurate the Tubb formation then fracture stimulate to increase production.

MIRU-SU. Kill well w/2% KCL fresh water. POH w/production equip. Perforate the following Tubb intervals w/a 4" casing gun, 2 JSPF at 180° phasing: 2424-2428, 2436-2444, 2450-2490, 2508-2528, 2531-2535. Plug well back to 2250' w/8/16 sand. RIH w/treating packer and 3-1/2" J-55 workstring. Above packer place a Baker 2.875" sidemount with a Lynes Sentry MK9-E downhole pressure-temperature gauge. Set packer at 2220'. Prepare to frac well with 40# HEC Gel, liquid CO2 and 8/16 Brady sand. Mix gel in 2% KCL fresh water.

0+2-NMOCD,SF 1-R.A. Sheppard HOU. Rm. 20.156 1-J.F. Nash HOU. Rm. 17.188 1-SBB
1-Amerada Hess 1-Amerigas 1-Cities Service 1-Conoco 1-CO2 in Action 1-Shell
1-Exxon 1-WF, Hobbs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steve Brownlee

TITLE Admin. Analyst

DATE 11-14-86

APPROVED BY Roy E. [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE DISTRICT SUPERVISOR

DATE 11-20-86

Frac down tubing as follows:

<u>Stage</u>	<u>Gel Vol (BBLS)</u>	<u>Clean Rate (BPM)</u>	<u>Blender Conc. (PPG)</u>	<u>CO2 Vol (BBLS)</u>	<u>Rate BPM</u>
Pad	105	14	0.0	157	21
First	38	14	12.5	57	21
Second	76	14	15.0	114	21
Flush	8	14	0.0	12	21
Total	227		67,830#	340	

Shut well in for 2 hours after frac job. Flow well back to flow tank to recover load water overnight. Clean out sandfill to 2650' with bulldog bailer. RIH w/production equip. Load backside w/packer fluid and pressure test annulus to 500#. Swab well down to recover load. RDMO-SU. Return well to production.