

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NMOCD District 2

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: LINN Energy	Contact: Brian Wall
Address: 2130 W Bender Blvd. - Hobbs, NM	Telephone No.: 575-942-8675
Facility Name: Barclay State Battery - Barclay State #2	Facility Type: Battery
Surface Owner: State	Mineral Owner: State
API No.: 3001529590	

LOCATION OF RELEASE

Unit Letter J	Section 02	Township 23S	Range 31E	Feet from the 1980	North/South Line South	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.33163 Longitude: -103.74577

NATURE OF RELEASE


Type of Release: Oil/Produced water	Volume of Release: 15bbls / 400bbls	Volume Recovered: 10bbls / 385bbls
Source of Release: Pump	Date and Hour of Occurrence: 10/5/2012 - 0730	Date and Hour of Discovery: 10/5/2012 - 0800
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade - NM BLM	
By Whom? Brian Wall	Date and Hour: 10/5/2012 -1419	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: received a phone call that the tanks were overflowing. Arrived to location and H pump was down on digital overload. H pump controls repaired.

Describe Area Affected and Cleanup Action Taken.* : Called a vac truck and electrician. All fluid was contained inside the firewall. The contaminated area inside the the firewall was excavated and hauled to Lealand for disposal. The area was backfilled with like material and compacted. There are areas that exceed the allowable limits for chlorides that will be addressed when the battery is closed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: EL Gonzales	Approved by District Supervisor:	
Title: Production Supervisor	Approval Date: 12/15/14	Expiration Date: N/A
E-mail Address: elgonzales@linnenergy.com	Battery area is to be fully delineated and remediation performed at close of facility. <input type="checkbox"/> attached	
Date: 11/17/14	Phone: 505-504-8002	

* Attach Additional Sheets If Necessary

2RP-1315