

Received 2/5/2015

NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Derringer 18 Fed Com #2H	Facility Type: Oil producing Well
Surface Owner: BLM	Mineral Owner: BLM
API No. 30-015-39758	

LOCATION OF RELEASE

Unit Letter E	Section 18	Township 20S	Range 29E	Feet from the 2150'	North/South Line North	Feet from the 330'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.5748558 Longitude -104.1211555

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: estimated 150 bbls PW	Volume Recovered: 125 bbls PW
Source of Release: SWD Transfer Polly Line	Date and Hour of Occurrence 12-29-14	Date and Hour of Discovery 12-29-14 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos	
By Whom? Zack Thomas	Date and Hour 12-29-14 5:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


Cause of the leak- 18 wheeler ran over and damaged the SWD discharge Line. The release was stopped by attaching nipple and valve to damaged line.

Describe Area Affected and Cleanup Action Taken.*

Affected area- The lease road at the entrance to the well pad.

Cleanup Action- Vacuum trucks were used to recover 125 bbls of standing produced water. Backhoe then scraped up contaminated soil and hauled to Lea Land Disposal. Soil samples were taken to confirm acceptable chloride levels.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Zack Thomas	Approved by Environmental Specialist:	
Title: Environmental Rep.	Approval Date: 2/6/2015	Expiration Date: NA
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2-5-15	FINAL	

Phone: 575-602-2188

2RP-2792