

**From:** [Rebecca Pons](#)  
**To:** [Patterson, Heather, EMNRD](#); [jlrobertson@blm.gov](mailto:jlrobertson@blm.gov)  
**Cc:** [Brett Fulks](#)  
**Subject:** Remediation Plan  
**Date:** Friday, August 28, 2015 8:21:05 AM  
**Attachments:** Devon Cotton Draw 10 Fed .pdf

---

Good Morning,

I have attached a Plan for Remediating the Devon Cotton Draw 10 Fed API 30-015-42126. Basically, there is a current excavation on site that is at 3' bgs. Due to the horizontal and vertical results of our delineation; SESI is proposing the following:

Further excavate the East and South wall of the current excavation to the extent the Chlorides are <1000 mg/kg to a depth of 18" this is due to the number of high voltage lines to the East of the excavation. Backfill the current excavation to a depth of 18" and line the entire excavation with a 20 mil liner. Backfilling with a layer of topsoil, so as not to impede the liner followed with like surface material and restore to grade. Please don't hesitate to contact me if you have any questions.

*Thank You*

*Rebecca Pons*

Safety & Environmental Solutions, Inc.  
703 East Clinton Street  
Hobbs, NM 88240  
Office: (575) 397-0510