

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 5/2/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Getty 24 Federal #11 CTB	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-015-31162
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
SE ¼	24	22S	31E					Eddy County, NM

Latitude N 32.37580° Longitude W 103.72616°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	50 bbls	Volume Recovered	45 bbls
Source of Release	Internal corrosion caused a hole in the bottom of the west oil tank	Date and Hour of Occurrence	07/10/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD, Jeffrey Robertson-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	07/10/2015 @ 3:27 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Internal corrosion caused a hole in the bottom of the west oil tank spilling 50 bbls of oil onto the ground. A vacuum truck recovered 45 bbls of oil and the tank was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 105' x 35' with all of the leak staying inside the firewall on location. Remediation was completed according to a remediation plan approved by Mike Bratcher of NMOCD via email on 09/30/2015 and by Shelly Tucker of the BLM on 09/28/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				OIL CONSERVATION DIVISION			
Printed Name:	Casey Summers			Approved by Environmental Specialist:			
Title:	NM Environmental Lead			Approval Date:	5/6/2016	Expiration Date:	N/A
E-mail Address:	casey_summers@oxy.com			Conditions of Approval:		Attached <input type="checkbox"/>	
Date:	4-27-16			Phone:		(575) 513-8289	
				FINAL			

* Attach Additional Sheets If Necessary

2RP-3169