District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Received 7/13/2016 NMOCD Artesia

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

	Release Notification and Corrective Action												
Name of Company Oxy Permian Ltd.						OPERATOR Contact Casey Summers			∐ Initi	al Report		Final Repo	
Address 6 Desta Drive, Midland, TX 79705						Telephone No. (575) 513-8289							
Facility Name Lost Tank 35 State #1 SWD Facility						Facility Type Battery							
Surface Owner State Mineral Owner						r API No. 30-015-40890							
		-	<u> </u>	NOEDE	EAGE		FRITTE	<u>, 50-015-</u>	40020				
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
			•	l cet nom the	140111	/ South Line	rect from the	Easuv	vest Line	County			
K <sub>_</sub>	35	21S	31E		<u></u>					Eddy County, NM			
<b>Latitude</b> <u>N 32.43482°</u> <b>Longitude</b> <u>W 103.74899°</u>													
NATURE OF RELEASE													
Type of Release Produced water						Volume of Release 18 bbls   Volume Recovered 15 bbls							
Source of Release Corrosion of nipple on the discharge line						Date and Hour of Occurrence O9/08/2015 Date and Hour of Discovery							
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? d Mike Bratcher, Heather Patterson- NMOCD							
By Whom? Kathy Purvis, BBC International						Date and Hour 09/08/2015 @ 3:27 pm							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
☐ Yes ☒ No  If a Watercourse was Impacted, Describe Fully.*						<u> </u>							
		,											
Describe Cause of Problem and Remedial Action Taken.*													
Internal corrosion of a steel nipple on the discharge line caused 18 bbls of produced water to leak onto the ground. A vacuum truck recovered 15 bbls of water and the nipple was replaced.													
Describe Area Affected and Cleanup Action Taken.*													
The affected area is inside the lined battery. Remediation was completed by removing the impacted soil from the lined battery and replacing it with clean													
soil.													
I hereby certif	fy that the in	nformation giv	en above	is true and compl	ete to t	he best of my l	nowledge and u	nderstan	d that purs	uant to NM(	OCD ru	les and	
public health	operators a or the envir	are required to onment. The	report an acceptance	d/or file certain re e of a C-141 repo	elease r	iotifications an	d perform correct	tive actio	ons for rele	ases which	may en	langer	
snould their o	perations na	ave failed to a	dequately	investigate and re	emedial	te contaminatio	n that pose a thre	eat to gro	und water	surface was	er hun	nan kealth	
or the environ federal, state,	iment. In ac	agition, NMO	CD accept	ance of a C-141 i	eport d	loes not relieve	the operator of r	esponsit	oility for co	mpliance w	ith any	other	
	$-\Lambda$	/ [					OIL CONS	SERV	ATION	DIVISIO	N		
Signature:	IN												
Printed Name: Casey Summers						Approved by Environmental Specialist:							
Title: NM Environmental Advisor						Approval Date: 7/14/2016 Expiration Date: N/A					_		
E-mail Address: Casey_Summers@oxy.com						Conditions of Approval:				Attached			
7 11 10-						FINAL At							
Date: Phone: (575) 513-8289 FINAL													