State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 S. St. Fran	cis Dr., Santa	a Fe, NM 87505	5	Sa	anta Fe	e, NM 875	05								
DADARSIS SALAN MANAGANA MANAGAN			Rele	ease Notific	cation	n and Co	orrective A	ction							
				🛛 Initia	al Report	\boxtimes	Final Report								
		each Explora				OPERATORInitial ReportFinal ReportContactJack Rose									
	and the second se			dland, TX 797		Telephone No. 432/683-6226 Facility Type Waterflood Satellite test Battery									
Facility Nar	ne Eastlar	nd Queen Ur	nit			Facility Typ	e Waterflood S	Satellite	test Batte	ry					
Surface Ow	ner State			Mineral (Owner	State			API No. 30-015-26095 Unit Number: 300337						
				LOCA	ATIO	N OF RE	LEASE								
Unit Letter							Feet from the	East/W	Vest Line County						
С	11	198	29E	990	North		990	West		Eddy					
	1	Latitu	de32.0	581395_°		Longitude	e104.0466	559°		-					
				NAT	FURE	OF REL	EASE								
Type of Rele	ase 3 bbls	oil/water mix				Volume of Release Est. 3 bbl			Volume Recovered 3 bbl						
		knocked ove urphy switch.		ound battery and i	rubbed	Date and Hour of Occurrence Est 9/6/16 11:30a.m.			Date and Hour of Discovery 9/6/16 4:00 pm						
Was Immedi	and the second se	Given?] No 🗌 Not R	equired	If YES, To Whom?									
Der Wilsens 9					equireu	Date and Hour 9/20/16 3:17pm									
By Whom? Was a Water		ched?				If YES, Volume Impacting the Watercourse.									
in us a mater			Yes 🛛	No											
switch openi Describe See attached I hereby cert regulations a public health should their or the enviro	ng and relea Area Af I Remediat ify that the ll operators or the environ operations I nment. In a	asing 3 bbls o fected and tion Plan. information g are required to have failed to	d Clean iven abov to report a e acceptan adequatel OCD acce	n Taken.*Leak d nto caliche well p up Action Ta e is true and comp nd/or file certain ce of a C-141 rep y investigate and ptance of a C-141	ad. Clear aken.* plete to t release r port by th remedia	the best of my notifications a ne NMOCD n te contaminat	hetted tank. knowledge and nd perform corre harked as "Final F ion that pose a th ye the operator of	understar ective acti Report" d reat to gr responsi	nd that pur ions for rel oes not rel round wate bility for c	suant to NM leases which ieve the ope r, surface w compliance	IOCD n n may e erator o ater, hu with an	rules and ndanger f liability uman health			
Signature:	Jus	M.	Glo	-se		OIL CONSERVATION DIVISION									
Printed Nam	e: Jack M.	Rose				Approved by	Environmental S	Specialis	.st:						
Title: Engine	eer					Approval Date:			Expiration Date:						
E-mail Addr	ess: bmarti	in@beachexp.	.com			Conditions of Approval:				Attached					
Date:	10/26/2016		Phone	:432/683-6226											

* Attach Additional Sheets If Necessary

Beach Exploration, Inc.

EQU #24 Location Spill Unit C, Sec 11, T-19-S R-29-E

Remediation Plan

October 26, 2016

Beach has contacted CMB Environmental (575-622-2012) out of Roswell New Mexico to assist in the remediation of the subject spill.


Using Google Earth images, location specifics and the original photos taken on 9-6-16 by Robert Kasuboski with the State Land Office, the area of the spill was delineated (see attached "EQU#24 Spill Size.pdf" and two original photos "EQU#24 9-6-16 pho1.jpeg" and "EQU #24 9-6-16 ph03.jpeg").

The "Site Assessment" from the OCD guidelines for this location was a score of "0" on a scale of "0-20".

Depth to Ground Water >100' (195' see attached PDF file SLO FW depth) Ranking Score = 0 Wellhead Protection Area >1000' from any water source Ranking Score = 0 Distance To Surface Water Body >1000' Ranking Score = 0

With a score of 0 - 9 requirements are to remediate the soil to Benzene (10 ppm), BTEX (50 ppm) and TPH (5000 ppm).

CMB Environmental's recommendation, based on the above information, is to remove all stained/saturated material to an approved site and then take a few samples in the excavated area at 3' and 6' to ensure remediation levels are acceptable. The area would then be backfilled with clean material. This recommendation was based on the original spill photos, the delineation of the spill and "Site Assessment" score of "0".





New Mexico Office of the State Engineer Water Column/Average Depth to Water

(A CLW###### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)		(R=POE been re O=orpha C=the fi closed)	(quarters are 1=NW 2=NE 3=SW 4=SE) (quarters are smallest to largest) (NAD83 UTM in meters) (In feet)												
POD Number		S	POD Sub- asin Cour	Contraction of the local	Q 16		Sec	Tws	Rng)	ζ Υ	Distance	Constitution of the second second	Depth Water	Water Column
CP 00626 POD2	1,43	mi	CP ED	3	2	1	03	19S	29E	587559 32.69426	9 3617779*	2300	240	195	45
CP 00626 POD1	1,46	m;	CP ED	2	3	1	03	19S	29E	58736	-200000	2350	286	247	39
CP 00863	2,8 1	1	ED	1	4	2	27	18S	29E	58834		4519 meter	320		
											Avera	age Depth to	Water:	221	feet
												Minimum	Depth:	195	feet
EQU#24										32.681	395 -1020466	Maximum	Depth:	247	feet
Record Count: 3															
Basin/County Search:Basin: CapitanCounty			y: E	ddy											
UTMNAD83 Ra	adius S	earch (in	meters):												
Easting (X): 589376.86				No	Northing (Y): 3616368.72 Radius: 4830										

*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.



