From:	Weaver, Crystal, EMNRD
To:	"Blaney, Karolina"; "Tucker, Shelly"; Bratcher, Mike, EMNRD
Subject:	RE: RDU 11 - C-141
Date:	Thursday, May 18, 2017 8:35:00 AM
Attachments:	1. 4197 - COAs and signed C-141 Initial.pdf
	2RP-2286.pdf

RE: WPX/RKI * RDU #11 * 30-015-24307 * 2RP-4197

Karolina,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4197.

PLEASE NOTE: I was also looking in the files for this site location to see if there were any old remediations that we needed an update on and I came across case number 2RP-2286. I attached the original C-141 to this email. That is all we have on record for this case. It is from before you came over to NM I think (2014), but if you have any additional information on it, it would be great if you could share it so we can move forward to hopefully closing this one out.

Thank you,

Crystal Weaver

Environmental Specialist OCD – Artesia District II 811 S. 1st Street Artesia, NM 88210 Office: 575-748-1283 ext. 101 Cell: 575-840-5963 Fax: 575-748-9720

From: Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]
Sent: Tuesday, May 2, 2017 3:28 PM
To: 'Tucker, Shelly' <stucker@blm.gov>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Subject: RE: RDU 11 - C-141

Good afternoon, Attached is the C-141 report for the RDU 11 spill. Please let me know if you have any questions or concerns. Thank you and have a great afternoon,

Karolina Blaney Environmental Specialist WPX Energy Office: (575) 885-7514 Cell: (970) 589-0743 karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Friday, April 21, 2017 9:57 AM
To: Tucker, Shelly <<u>stucker@blm.gov</u>>; Weaver, Crystal, EMNRD <<u>Crystal.Weaver@state.nm.us</u>>;
Bratcher, Mike, EMNRD <<u>mike.bratcher@state.nm.us</u>>
Subject: RDU 11 - initial spill notification

Good morning,

WPX had a spill yesterday, 4-20-17 at 1:20 pm at the RDU 11 pad. API # 30-015-24307, qtr/qtr O-S22-T26S-R30E. The spill was caused by human error; the equipment setup was changed and the calibration guys were given a wrong information. They closed a valve that should've been open which resulted in over-pressuring an above ground poly line. Approximately 50 bbls of oil and water was spilled off location north and west of the location. All free liquids were recovered with a vac truck and the recovered volume will be included in the C-141 report.

WPX would like to ask for BLM's permission to excavate the top 1-2' of the impacted area to prevent from vertical migration. The area will be sampled after the excavation activities are completed. There are no arch sites at the spill location.

Please let me know if you need any additional information.

Thank you and have a great weekend.

Karolina Blaney Environmental Specialist WPX Energy Office: (575) 885-7514 Cell: (970) 589-0743 karolina.blaney@wpxenergy.com