

Venegas, Victoria, EMNRD

From: Gloria Garza <ggarza@cimarex.com>
Sent: Monday, February 17, 2020 8:56 AM
To: EMNRD-OCD-District1spills
Cc: Griswold, Jim, EMNRD; Honea, Tammy; Joshua Jones
Subject: [EXT] Cimarex Reportable Spill - Caudill South 21 Fee

All,

We had a release yestserday at the Caudill South 21 Fee Battery. The produced water tank developed a hole due to corrosion. We got a vacuum truck out to location to pull water from the tank and a second truck to remove the standing fluid out of containment.

The well is shut in and the damaged tank is isolated/LOTO until we can asses the situation. We will remove the gravel and schedule/request the state to inspect the liner.

Cause of Spill: Corrosion
Material: Produced Water
Spilled: 30 Barrels (bbls)
Recovered: 30 Barrels (bbls)
Was Spill Contained: Yes
Is Containment Lined: Yes

Well Details

API: 30-025-37925

Well Name: CAUDILL SOUTH 21 FEE #002H

Operator: CIMAREX ENERGY CO.

Pools: [10830] CAUDILL;PERMO UPPER PENN

ULSTR: L-21-15S-36E

Footages: 2000 FSL & 940 FWL

County: Lea

District: Hobbs

I will submit a C-141 online.

Gloria Garza

From: XEC Apps <DONOTREPLY_DEVAPPS@cimarex.com>
Sent: Sunday, February 16, 2020 9:16 PM
Subject: New Incident Created

New Incident Created 22930

PDF Report

Incident Type: Spill - Agency Reportable
Sub Type: Agency Reportable
Severity Level: Level 2
District: Permian Basin-Northeast
Department: Production
Property Name: CAUDILL SOUTH 21 FEE 2H
Reported By: Robert Quesada
Reported By Phone Number: 4323013170
Incident Time: 2/16/2020 01:30 PM
Completed By: Joshua Jones on 02/16/2020
Contractor Involved: No

Operation

pumper making rounds

Cause of Spill: Corrosion

Material: Produced Water

Spilled: 30 Barrels (bbls)

Recovered: 30 Barrels (bbls)

Was Spill Contained: Yes

Is Containment Lined: Yes

Description

Pumper arrived on location to find water in gravel lined containment, upon searching found a hole in the bottom off 500bbl water tank.

Comment

Called two vacuum and got containment sucked out and tank sucked out gravel was moved back to reveal liner and to serve as a low spot to pull water from. will evaluate further for repair needed