Venegas, Victoria, EMNRD

From: Gloria Garza <ggarza@cimarex.com>
Sent: Tuesday, May 12, 2020 8:57 AM
To: EMNRD-OCD-District1spills

Cc: Griswold, Jim, EMNRD; Honea, Tammy; Ronald Hayes; Laci Luig

Subject: [EXT] RE: Cimarex Reportable Spill - Caudill South 21 Fee

Good Morning!

We have moved back the gravel in the area where the spill occurred, exposed the liner and we are requesting a field visit to inspect the liner and give permission to back fill.

Please call if you have any questions.

Thank you,

Gloria Garza 432.234.3204

From: Gloria Garza

Sent: Monday, February 17, 2020 9:56 AM

To: emnrd-ocd-district1spills (emnrd-ocd-district1spills@state.nm.us) <emnrd-ocd-district1spills@state.nm.us>

Cc: 'Griswold, Jim, EMNRD' <Jim.Griswold@state.nm.us>; tammy honea (thonea@slo.state.nm.us)

<thonea@slo.state.nm.us>; Joshua Jones <JJones2@cimarex.com>

Subject: Cimarex Reportable Spill - Caudill South 21 Fee

All,

We had a release yesterday at the Caudill South 21 Fee Battery. The produced water tank developed a hole due to corrosion. We got a vacuum truck out to location to pull water from the tank and a second truck to remove the standing fluid out of containment.

The well is shut in and the damaged tank is isolated/LOTO until we can assess the situation. We will remove the gravel and schedule/request the state to inspect the liner.

Cause of Spill: Corrosic Material: Produced Wate Spilled: 30 Barrels (bbls: Recovered: 30 Barrels (Was Spill Contained: Y

Well Details

API: 30-025-37925

Well Name: CAUDILL SOUTH 21 FEE #002H

Operator: CIMAREX ENERGY CO.

Pools: [10830] CAUDILL; PERMO UPPER PENI

ULSTR: L-21-15S-36E

Footages: 2000 FSL & 940 FWL

Country I --

I will submit a C-141 online.

Gloria Garza 432.234.3204

From: XEC Apps < DONOTREPLY DEVAPPS@cimarex.com>

Sent: Sunday, February 16, 2020 9:16 PM

Subject: New Incident Created

New Incident Created 22930

PDF Report

Incident Type: Spill - Agency Reportable

Sub Type: Agency Reportable

Severity Level: Level 2

District: Permian Basin-Northeast

Department: Production

Property Name: CAUDILL SOUTH 21 FEE 2H

Reported By: Robert Quesada

Reported By Phone Number: 4323013170

Incident Time: 2/16/2020 01:30 PM

Completed By: Joshua Jones on 02/16/2020

Contractor Involved: No

Operation

pumper making rounds

Cause of Spill: Corrosion Material: Produced Water Spilled: 30 Barrels (bbls) Recovered: 30 Barrels (bbls) Was Spill Contained: Yes Is Containment Lined: Yes

Description

Pumper arrived on location to find water in gravel lined containment, upon searching found a hole in the bottom off 500bbl water tank.

Comment

Called two vacuum and got containment sucked out and tank sucked out gravel was moved back to reveal liner and to serve as a low spot to pull water from. will evaluate further for repair needed

Automated Message Sent By Radar: https://apps.cimarex.com/Radar/usersetup