

Permit Comments

Operator: YATES PETROLEUM CORPORATION , 25575

Well: PADRON BGM STATE COM. #001

User Name	Comment	Comment Date
	30-015-33959	
DCAFFALL	Sources at Yates Petroleum Corporation have relayed information to me that they believe there will not be enough H2S found from the surface through the Precambrian Formation to meet the OCDs minimum requirements for the submission of a contingency plan per Rule 118.	2/14/2005
DCAFFALL	Any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines with approved general permit on file.	2/14/2005
DCAFFALL	BOPE PROGRAM: A 5000# Double Ram BOPE will be installed on the 9 5/8" casing and tested daily for operational.	2/14/2005
DCAFFALL	Correction on H2S Comment from the Precambrian Formation to the Morrow Formation.	2/14/2005