

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/14/2014

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc.	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name: Skelly Unit #14	Facility Type: Oil Producer

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-05322
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter L	Section 21	Township 17S	Range 31E	Feet from the 1980	North/South Line South	Feet from 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------	------------------------	-------------

Latitude: 32.8182612307726 Longitude -103.881153130687

NATURE OF RELEASE

Type of Release: Produced water/crude	Volume of Release 2bbls/5bbls	Volume Recovered 0/3bbls
Source of Release: Poly Pipeline	Date and Hour of Occurrence 9/17/2012	Date and Hour of Discovery 09/17/12 11:00 A.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD Terry Gregston BLM	
By Whom? Joe Hernandez	Date and Hour: 09/17/2012 5PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*

While marking the lease a spill was located where a 3" polyline came apart at the fusion weld.

Describe Area Affected and Cleanup Action Taken.

There was a 4"X8' area affected a vacuum truck was utilized to recover 3bbls. DFSI was retained to fully remediate the site according to NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<u>OIL CONSERVATION DIVISION</u>	
Signature: <i>Fred B Wall</i>		Approved by Environmental Specialist:	
Printed Name: Brian Wall			
Title: Construction Foreman II		Approval Date: 10/20/2014	Expiration Date: NA
E-mail Address: bwall@linenergy.com		Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 07/03/2014 Phone: 806-367-0645			

* Attach Additional Sheets If Necessary

2RP-1312