

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 4/14/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company	Devon Energy Production	Contact	Jake Harrington, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	432-214-5175
Facility Name	Cotton Draw Unit 153H	Facility Type	Oil
Surface Owner	Federal	Mineral Owner	Federal
		API No.	30-015-38535

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	3	25S	31E	200	FNL	1980	FEL	Eddy

Latitude: 32.16613000

Longitude: -103.7631000

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 15bbls	Volume Recovered 15bbls
Source of Release Tank Overflow	Date and Hour of Occurrence 10/6/12 @ 3:00 AM	Date and Hour of Discovery 10/6/12 @ 3:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, OCD Mike Bratcher, BLM	
By Whom? Gracie Bustamante	Date and Hour Jim Amos OCD 10/8/12 @ 3:45 PM Mike Bratcher, BLM 10/8/12 @ 3:34 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

At the Cotton Draw Unit 153H Battery, the scada pack battery lost connection after blowing a fuse that was caused by the cold weather, resulted in a 15bbl spill of produced water.

Describe Area Affected and Cleanup Action Taken.*

At the Cotton Draw Unit 153H Battery, the scada pack battery lost connection after blowing a fuse that was caused by the cold weather, resulted in a 15bbl spill of produced water. After the battery failed the water transfer pump turned off which allowed the water tanks to fill up and overflow. By the time the night rider arrived the produced water was spilling over into the lined containment. The night rider immediately contacted the pumper who then contacted a wash crew and vacuum truck. They washed and cleaned the containment, recovering 15bbls of produced water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Sheila Fisher	Approved by Environmental Specialist:		
Title: Field Admin Support	Approval Date: 4/20/2016	Expiration Date: N/A	
E-mail Address: Sheila.Fisher@dmn.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 4/6/16 Phone: 575.748.1829	FINAL		

* Attach Additional Sheets If Necessary

2RP-1329