

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Received 5/2/2016  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Cedar Canyon 15 Fed Com #5H	Facility Type	Satellite

Surface Owner	BLM	Mineral Owner		API No.	30-15-42421
---------------	-----	---------------	--	---------	-------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	15	24S	29E					Eddy County, NM

Latitude N 32.22168° Longitude W 103.98029°

**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	40 bbls oil, 100 bbls produced water	Volume Recovered	100 bbls
Source of Release	A broken water pump coupling caused the water tanks to spill over	Date and Hour of Occurrence	05/28/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; James Amos- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	05/29/2015 @ 10:02am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

A broken water pump coupling caused the water tanks to spill 40 bbls of oil and 100 bbls of produced water onto the ground. A vacuum truck recovered 100 bbls of fluids and the coupling was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 100' x 45' with most of the leak staying on location. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCD via email on 08/19/2015 and Shelly Tucker of the BLM via email on 08/19/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b><u>OIL CONSERVATION DIVISION</u></b>			
Printed Name:	Casey Summers	Approved by Environmental Specialist:			
Title:	NM Environmental Advisor	Approval Date:	5/4/2016	Expiration Date:	N/A
E-mail Address:	Casey_Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>	
Date:	4-27-16	Phone:	(575) 513-8289	FINAL	

\* Attach Additional Sheets If Necessary

2RP-3062