

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report


Name of Company: XTO Energy OGRID: BOPCO:260737	Contact: Kyle Littrell
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331
Facility Name: PLU 387 Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No: 30-015-41185	

### LOCATION OF RELEASE

Unit Letter D	Section 13	Township 25S	Range 30E	Feet from the 30	North/South Line North	Feet from the 321	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	---------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.137664 Longitude -103.841930 NAD83

### NATURE OF RELEASE

Type of Release Produced water	Volume of Release 631 bbl	Volume Recovered 600 bbl
Source of Release Riser	Date and Hour of Occurrence 8/9/2018, AM	Date and Hour of Discovery 8/9/2018, 1:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Maria Pruett (NMOCD), Jim Amos and Shelly Tucker (BLM)	
By Whom? Amy Ruth	Date and Hour: 8/10/2018, 10:10 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Release occurred because of corrosion in SWD riser. Lease operator was able to stop flow of water to pipeline. Riser was repaired and tested before returning to service.		
Describe Area Affected and Cleanup Action Taken.* Release occurred at SWD riser near lease road. The area around the riser had been excavated for upgrades, and the majority of fluid stayed within this excavation. Vacuum trucks were dispatched and recovered 540bbl from the excavation, and 60bbl from the surface. An environmental contractor has been retained to assist with remediation efforts.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 08/22/18	Expiration Date: N/A
E-mail Address: Amy_Ruth@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/22/2018 Phone: 432-661-0571	N/A	2RP-4946

\* Attach Additional Sheets If Necessary

A#: pMAP1823448718

I#: pMAP1823448718