Office 🐂	-	New Mexi				n C-103
District I	Energy, Minerals	and Natura	l Resources	WELL ADING		<u>ch 4, 2004</u>
\$625 N. French Dr., Hobbs, NM 88240				WELL API NO. 30-005-63593		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERV			5. Indicate Type	of Lease	·····
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South			STATE		<u> </u>
District IV	Santa Fe	e, NM 875	05	6. State Oil & G	as Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				VO-2073		
SUNDRY NOTIC	CES AND REPORTS ON ALS TO DRILL OR TO DEEL		BACK TO A	7. Lease Name Dice State Unit	or Unit Agreemen	t Name
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ATION FOR FERMIT (FOR	234	8678970	8. Well Number	r	
1. Type of Well: Oil Well Gas Well X			a is	1	•	
2. Name of Operator		60 . S	w w	9. OGRID Num	iber	
Yates Petroleum Corporation		an an	CV al B	025575		
3. Address of Operator 105 South Fourth Street, Artesia, N	N 99310	87.178	6 Nr. 3	10. Pool name of Undesignated Pr		
4. Well Location	IVI 00210	<del> 3</del> d	<u>6</u>	Ondesignated FI		. <del></del>
Unit Letter J : 19	80 feet from the			980 feet from	the East	line
			line and 610 1			-
Section 22		IOS Rang	ge 26E	and the second sec	aves County	
ne senten en la serie de la La serie de la s	11. Elevation (Show wh			)		
Pit or Below-grade Tank Application (Fer	nit or below grade tank clea	3728'G		d)		
Pit Location: ULSectTwp					nonwest fresh meters	-11
-					nearest fresb water w	en
Distance from nearest surface water			SectTwp	Rng	;	
feet from theline and	feet from the	line				
NOTICE OF IN			SUB	SEQUENT RI	EPORT OF:	
	TENTION TO: PLUG AND ABANDON		SUB REMEDIAL WOR		EPORT OF: ALTERING CAS	
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS		SUB REMEDIAL WOR COMMENCE DRI		EPORT OF: ALTERING CAS	X
	TENTION TO: PLUG AND ABANDON		SUB REMEDIAL WOR		EPORT OF: ALTERING CAS PLUG AND	X
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE		SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI		EPORT OF: ALTERING CAS PLUG AND	X
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION		SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER:	SEQUENT RI K	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN	
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	y state all pe	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: rtinent details, an	SEQUENT RI K	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN	IT
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] OTHER: 13. Describe proposed or compl of starting any proposed wor or recompletion. 6/11/04 – Reached TD 6329' at 9:30	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly ck). SEE RULE 1103. F	y state all pe	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: Trinent details, an Completions: At	SEQUENT RI K HLLING OPNS.[ ND d give pertinent da tach wellbore diag	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN attes, including estingtram of proposed of	IT
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] OTHER: 13. Describe proposed or compl of starting any proposed wor or recompletion. 6/11/04 – Reached TD 6329' at 9:30 6003'. 6/16/04 – Tagged fish at 5700'. Jarri	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly tk). SEE RULE 1103. F AM. Set cement plug w ng on fish, no movement	y state all performed for Multiple	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: rtinent details, an Completions: At C" with additives well.	SEQUENT RI K ILLING OPNS ND d give pertinent da tach wellbore diag at 6329'. WOC	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN utes, including esting gram of proposed of Dressed off cemen	IT mated da completion
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] OTHER: 13. Describe proposed or completion of starting any proposed word or recompletion. 6/11/04 - Reached TD 6329' at 9:30 6003'. 6/16/04 - Tagged fish at 5700'. Jarri 6/17/04 - Set plug #1 - 35 sx "C" Net	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly tk). SEE RULE 1103. F AM. Set cement plug w ang on fish, no movement at from 5700'-5600'. Set	y state all pe For Multiple with 100 sx "(	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: rtinent details, an Completions: At C'' with additives well. 35 sx "C" Neat fr	SEQUENT RI K ILLING OPNS ND d give pertinent da tach wellbore diag at 6329'. WOC om 5122'-5022'.	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN ates, including estin gram of proposed of Dressed off cemer Set plug #3 - 35 s	IT mated da completion at plug to x "C" No
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] OTHER: 13. Describe proposed or completion of starting any proposed worder or recompletion. 6/11/04 - Reached TD 6329' at 9:30 6003'. 6/16/04 - Tagged fish at 5700'. Jarri 6/17/04 - Set plug #1 - 35 sx "C" Net from 4454'-4354'. Set plug #4 - 35	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly tk). SEE RULE 1103. F AM. Set cement plug w ng on fish, no movement at from 5700'-5600'. Se sx "C" Neat from 2158'-	y state all pe For Multiple t. Will plug et plug #2 - 2058'. Set p	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: Trinent details, an Completions: At C" with additives well. 35 sx "C" Neat fr plug #5 - 50 sx "C	SEQUENT RI K ILLING OPNS ND d give pertinent da tach wellbore diag at 6329'. WOC om 5122'-5022'.	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN ates, including estin gram of proposed of Dressed off cemer Set plug #3 - 35 s	IT mated dz completion at plug to x "C" No
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] OTHER: 13. Describe proposed or completion of starting any proposed worder or recompletion. 6/11/04 - Reached TD 6329' at 9:30 6003'. 6/16/04 - Tagged fish at 5700'. Jarri 6/17/04 - Set plug #1 - 35 sx "C" Ne from 4454'-4354'. Set plug #4 - 35 Tagged in/out plug at 551'. Set plug	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly tk). SEE RULE 1103. F AM. Set cement plug w ng on fish, no movement at from 5700'-5600'. Se sx "C" Neat from 2158'- #6 – 30 sx "C" with add	y state all pe or Multiple t. Will plug et plug #2 - 2058'. Set p itives from 0	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: Trinent details, an Completions: At C" with additives well. 35 sx "C" Neat fro plug #5 - 50 sx "C 60'-surface.	SEQUENT RI K ILLING OPNS ND d give pertinent da tach wellbore diag at 6329'. WOC om 5122'-5022'.	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN ates, including estin gram of proposed of Dressed off cemer Set plug #3 - 35 s	IT mated dz completion at plug to x "C" No
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] OTHER: 13. Describe proposed or compl of starting any proposed wo or recompletion. 6/11/04 - Reached TD 6329' at 9:30 6003'. 6/16/04 - Tagged fish at 5700'. Jarri 6/17/04 - Set plug #1 - 35 sx "C" Ne from 4454'-4354'. Set plug #4 - 35 Tagged in/out plug at 551'. Set plug 6/18/04 - WELL IS PLUGGED ANI	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly tk). SEE RULE 1103. F AM. Set cement plug w ng on fish, no movement at from 5700'-5600'. Se sx "C" Neat from 2158'- #6 – 30 sx "C" with add DABANDONED. FINA	y state all per For Multiple ith 100 sx "( t. Will plug et plug #2 – 2058'. Set p itives from ( AL REPORT	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: artinent details, an Completions: At C" with additives well. 35 sx "C" Neat fr plug #5 - 50 sx "C 60'-surface. [.	SEQUENT RI K ILLING OPNS ND d give pertinent da tach wellbore diag at 6329'. WOC om 5122'-5022'. ; C'' with additives f	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN utes, including estin gram of proposed of Dressed off cemen Set plug #3 – 35 st from 657'-557'. W	IT mated da completion t plug to x "C" No /OC.
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] OTHER: 13. Describe proposed or compl of starting any proposed wor or recompletion. 6/11/04 - Reached TD 6329' at 9:30 6003'. 6/16/04 - Tagged fish at 5700'. Jarri 6/17/04 - Set plug #1 - 35 sx "C" Ne from 4454'-4354'. Set plug #4 - 35 Tagged in/out plug at 551'. Set plug 6/18/04 - WELL IS PLUGGED ANI NOTE: Reaffirmed plugging orders	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly tk). SEE RULE 1103. F AM. Set cement plug w ng on fish, no movement at from 5700'-5600'. Se sx "C" Neat from 2158'- #6 – 30 sx "C" with add DABANDONED. FINA	y state all per For Multiple ith 100 sx "( t. Will plug et plug #2 – 2058'. Set p itives from ( AL REPORT	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: artinent details, an Completions: At C" with additives well. 35 sx "C" Neat fr plug #5 - 50 sx "C 60'-surface. [.	SEQUENT RI K ILLING OPNS ND d give pertinent da tach wellbore diag at 6329'. WOC om 5122'-5022'. ; C'' with additives f	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN utes, including estin gram of proposed of Dressed off cemen Set plug #3 – 35 st from 657'-557'. W	IT mated da completion at plug to x "C" No /OC.
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] OTHER: 13. Describe proposed or completion of starting any proposed worder of starting any proposed or completion. 6/11/04 - Reached TD 6329' at 9:30 6/16/04 - Tagged fish at 5700'. Jarrie 6/17/04 - Set plug #1 - 35 sx "C" Ne from 4454'-4354'. Set plug #4 - 35 Tagged in/out plug at 551'. Set plug 6/18/04 - WELL IS PLUGGED ANI NOTE: Reaffirmed plugging orders circ sub and bumper jars in hole.	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly ck). SEE RULE 1103. F AM. Set cement plug w ng on fish, no movement at from 5700'-5600'. Se sx "C" Neat from 2158'- #6 – 30 sx "C" with add DABANDONED. FINA with OCD representative	y state all pe For Multiple ith 100 sx " t. Will plug et plug #2 2058'. Set j itives from C AL REPORT c, Mike Brate	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: Trinent details, an Completions: At C" with additives well. 35 sx "C" Neat fr plug #5 – 50 sx "C 60'-surface. C. cher, on 6-17-04.	SEQUENT RI K ILLING OPNS.[ ND d give pertinent da tach wellbore diag at 6329'. WOC cm 5122'-5022' C" with additives f Left test tools, 5 d	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN utes, including esting gram of proposed of Dressed off cemer Set plug #3 – 35 st from 657'-557'. W	IT mated da completion at plug to x "C" Ne /OC. -in sub,
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] OTHER: 13. Describe proposed or completion of starting any proposed worder of starting any proposed or completion. 6/11/04 - Reached TD 6329' at 9:30 6/16/04 - Tagged fish at 5700'. Jarri 6/17/04 - Set plug #1 - 35 sx "C" Ne from 4454'-4354'. Set plug #4 - 35 Tagged in/out plug at 551'. Set plug 6/18/04 - WELL IS PLUGGED ANI NOTE: Reaffirmed plugging orders circ sub and bumper jars in hole. I hereby certify that the information a	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly ck). SEE RULE 1103. F AM. Set cement plug w ng on fish, no movement at from 5700'-5600'. Se sx "C" Neat from 2158'- #6 – 30 sx "C" with add <u>DABANDONED</u> . FINA with OCD representative	y state all pe For Multiple ith 100 sx " t. Will plug et plug #2 2058'. Set p itives from ( AL REPORT c, Mike Brate te to the bess	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: Trinent details, an Completions: At C" with additives well. 35 sx "C" Neat fr plug #5 - 50 sx "C 60'-surface. C. cher, on 6-17-04.	SEQUENT RI K ILLING OPNS.[ ND d give pertinent da tach wellbore diag at 6329'. WOC om 5122'-5022' C" with additives f Left test tools, 5 d e and belief. I furt	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN utes, including esting gram of proposed of Dressed off cerner Set plug #3 – 35 st from 657'-557'. W	IT mated da completion at plug to x "C" Ne /OC. -in sub, it or below
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] OTHER: 13. Describe proposed or completion. 6/11/04 - Reached TD 6329' at 9:30 6003'. 6/16/04 - Tagged fish at 5700'. Jarri 6/17/04 - Set plug #1 - 35 sx "C" Ne from 4454'-4354'. Set plug #4 - 35 Tagged in/out plug at 551'. Set plug 6/18/04 - WELL IS PLUGGED ANI NOTE: Reaffirmed plugging orders circ sub and bumper jars in hole. I hereby certify that the information a grade tank has been/will be constructed or	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly tk). SEE RULE 1103. F AM. Set cement plug w ng on fish, no movement at from 5700'-5600'. Se sx "C" Neat from 2158'- #6 – 30 sx "C" with add <u>DABANDONED</u> . FINA with OCD representative bove is true and complet closed according to NMOCD	y state all pee For Multiple ith 100 sx "f t. Will plug et plug #2 – 2058'. Set p itives from 6 AL REPORT c, Mike Brate te to the best guidelines	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: Trinent details, an Completions: At C'' with additives well. 35 sx "C" Neat fr plug #5 – 50 sx "C 60'-surface. Cher, on 6-17-04.	SEQUENT RI K ILLING OPNS ND d give pertinent da tach wellbore diag at 6329'. WOC. om 5122'-5022'. C'' with additives f Left test tools, 5 d e and belief. I furt or an (attached) alter	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN ites, including estin gram of proposed of Dressed off cerner Set plug #3 – 35 st from 657'-557'. W trill collars, screw ther certify that any p rnative OCD-approve	IT
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion. 6/11/04 - Reached TD 6329' at 9:30 6003'. 6/16/04 - Tagged fish at 5700'. Jarri 6/17/04 - Set plug #1 - 35 sx "C" Net from 4454'-4354'. Set plug #4 - 35 Tagged in/out plug at 551'. Set plug 6/18/04 - WELL IS PLUGGED ANI NOTE: Reaffirmed plugging orders circ sub and bumper jars in hole. I hereby certify that the information at grade tank has been/will be constructed or SIGNATURE:	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly tk). SEE RULE 1103. F AM. Set cement plug w mg on fish, no movement at from 5700'-5600'. Se sx "C" Neat from 2158'- #6 – 30 sx "C" with add <u>D ABANDONED</u> . FINA with OCD representative bove is true and complet closed according to NMOCD	y state all pe For Multiple ith 100 sx " t. Will plug et plug #2 - 2058'. Set j itives from C AL REPORT c, Mike Brate te to the bess guidelines	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: Intinent details, and Completions: At C' with additives well. 35 sx "C" Neat fro plug #5 – 50 sx "C 60'-surface. C. cher, on 6-17-04.	SEQUENT RI K	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN utes, including estin gram of proposed of Dressed off cemer Set plug #3 – 35 st from 657'-557'. W trill collars, screw ther certify that any p rnative OCD-approve DATE: June 30, 2	IT
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed wordow or recompletion. 6/11/04 - Reached TD 6329' at 9:30 6003'. 6/16/04 - Tagged fish at 5700'. Jarri 6/17/04 - Set plug #1 - 35 sx "C" Net from 4454'-4354'. Set plug #4 - 35 from 4454'-4354'. Set plug #1. Set plug for a start plug at 551'. Set plug for a start plug at 551'. Set plug for a start plu	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly tk). SEE RULE 1103. F AM. Set cement plug w mg on fish, no movement at from 5700'-5600'. Se sx "C" Neat from 2158'- #6 – 30 sx "C" with add <u>D ABANDONED</u> . FINA with OCD representative bove is true and complet closed according to NMOCD	y state all pe For Multiple ith 100 sx " t. Will plug et plug #2 - 2058'. Set j itives from C AL REPORT c, Mike Brate te to the bess guidelines	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: Trinent details, an Completions: At C'' with additives well. 35 sx "C" Neat fr plug #5 – 50 sx "C 60'-surface. Cher, on 6-17-04.	SEQUENT RI K	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN utes, including estin gram of proposed of Dressed off cerner Set plug #3 – 35 st from 657'-557'. W trill collars, screw ther certify that any p rnative OCD-approve DATE: June 30, 2 aone No. 505-748-	X "C" Ne it or below 2004 -1471_
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion. 6/11/04 - Reached TD 6329' at 9:30 6003'. 6/16/04 - Tagged fish at 5700'. Jarri 6/17/04 - Set plug #1 - 35 sx "C" Net from 4454'-4354'. Set plug #4 - 35 Tagged in/out plug at 551'. Set plug 6/18/04 - WELL IS PLUGGED ANI NOTE: Reaffirmed plugging orders circ sub and bumper jars in hole. I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE:	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly tk). SEE RULE 1103. F AM. Set cement plug w mg on fish, no movement at from 5700'-5600'. Se sx "C" Neat from 2158'- #6 – 30 sx "C" with add <u>D ABANDONED</u> . FINA with OCD representative bove is true and complet closed according to NMOCD	y state all pe For Multiple ith 100 sx " t. Will plug et plug #2 - 2058'. Set j itives from C AL REPORT c, Mike Brate te to the bess guidelines	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: Intinent details, and Completions: At C' with additives well. 35 sx "C" Neat fro plug #5 – 50 sx "C 60'-surface. C. cher, on 6-17-04.	SEQUENT RI K	EPORT OF: ALTERING CAS PLUG AND ABANDONMEN utes, including estin gram of proposed of Dressed off cemer Set plug #3 – 35 st from 657'-557'. W trill collars, screw ther certify that any p rnative OCD-approve DATE: June 30, 2	X "C" Ne /OC. -in sub, it or below ed plan



MT - Prod. 2/23/05 NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON Governor **Betty Rivera Cabinet Secretary** 

3-28-05 OK to TELEASE

Lori Wrotenbery Director **Oil Conservation Division** 

Yates Petroleum Corporation 105 South 4th Street Artesia, New Mexico 88210

Form C-103 Report of Plugging for your Dice State Unit #1- Sec. 22-TIOS-R26E 30-005-63593 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

RECEIVED

MAR 0 3 2005

1. All pits have been filled and leveled.

**1**2. Rat hole and cellar have been filled and leveled.

A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)

. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.

The dead men and tie downs have been cut and removed.

1. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.

All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

date 2/23/05 g in change

Van Barton Field Rep. II