Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources	October 13, 2009
1625 N French Dr , Hobbs, NM 88240	WELL API NO.
District II 1301 W Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-21142 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE S
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr , Santa Fe, NM	o. State Off & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Gissler AV
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	8. Well Number
1. Type of Well: Oil Well Gas Well Other P&A	9 ~
2. Name of Operator	9. OGRID Number
Yates Petroleum Corporation	025575
3. Address of Operator	10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210	Eagle Creek; San Andres
4. Well Location	-
Unit Letter C · 330 feet from the North line and	1650 feet from the West line
Section 23 Township 17S Range 25E	NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3500'GR	
3500 OK	
12 Cl 1 A	D O41 D-4-
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
	ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE	
BOWN TOLE COMMITTEE	
OTHER. OTHER.	
	and give pertinent dates, including estimated date
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: Of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar	
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	
 Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 	empletions: Attach wellbore diagram of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with G 	empletions: Attach wellbore diagram of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 	empletions: Attach wellbore diagram of R/JB to 589'. RIH open ended to 1280'.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement. 	mpletions: Attach wellbore diagram of R/JB to 589'. RIH open ended to 1280'. with 2% CaCl. WOC. Tagged at 640'.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 	empletions: Attach wellbore diagram of R/JB to 589'. RIH open ended to 1280'. with 2% CaCl. WOC. Tagged at 640'. oped out casing.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and 	empletions: Attach wellbore diagram of R/JB to 589'. RIH open ended to 1280'. with 2% CaCl. WOC. Tagged at 640'. oped out casing.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 	empletions: Attach wellbore diagram of PR/JB to 589'. RIH open ended to 1280'. with 2% CaCl. WOC. Tagged at 640'. oped out casing. d cut off anchors. WELL IS PLUGGED
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and 	empletions: Attach wellbore diagram of PR/JB to 589'. RIH open ended to 1280'. with 2% CaCl. WOC. Tagged at 640'. oped out casing. d cut off anchors. WELL IS PLUGGED
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and 	empletions: Attach wellbore diagram of a R/JB to 589°. RIH open ended to 1280°. with 2% CaCl. WOC. Tagged at 640°. oped out casing. d cut off anchors. WELL IS PLUGGED
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and 	empletions: Attach wellbore diagram of PR/JB to 589'. RIH open ended to 1280'. with 2% CaCl. WOC. Tagged at 640'. oped out casing. d cut off anchors. WELL IS PLUGGED
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and 	empletions: Attach wellbore diagram of AR/JB to 589'. RIH open ended to 1280'. With 2% CaCl. WOC. Tagged at 640'. Oped out casing. WELL IS PLUGGED RECEIVED OCT 13 2011
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and 	empletions: Attach wellbore diagram of a R/JB to 589°. RIH open ended to 1280°. with 2% CaCl. WOC. Tagged at 640°. oped out casing. d cut off anchors. WELL IS PLUGGED
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and 	empletions: Attach wellbore diagram of AR/JB to 589'. RIH open ended to 1280'. With 2% CaCl. WOC. Tagged at 640'. Oped out casing. WELL IS PLUGGED RECEIVED OCT 13 2011
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar an AND ABANDONED. 	empletions: Attach wellbore diagram of AR/JB to 589'. RIH open ended to 1280'. With 2% CaCl. WOC. Tagged at 640'. Oped out casing. WELL IS PLUGGED RECEIVED OCT 13 2011
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and 	empletions: Attach wellbore diagram of AR/JB to 589'. RIH open ended to 1280'. With 2% CaCl. WOC. Tagged at 640'. Oped out casing. WELL IS PLUGGED RECEIVED OCT 13 2011
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar an AND ABANDONED. 	empletions: Attach wellbore diagram of AR/JB to 589'. RIH open ended to 1280'. With 2% CaCl. WOC. Tagged at 640'. Oped out casing. WELL IS PLUGGED RECEIVED OCT 13 2011
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar an AND ABANDONED. Spud Date. Rig Release Date.	R/JB to 589°. RIH open ended to 1280°. with 2% CaCl. WOC. Tagged at 640°. oped out casing. d cut off anchors. WELL IS PLUGGED OCT 13 2011 NMOCD ARTESIA
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar an AND ABANDONED. 	R/JB to 589°. RIH open ended to 1280°. with 2% CaCl. WOC. Tagged at 640°. oped out casing. d cut off anchors. WELL IS PLUGGED OCT 13 2011 NMOCD ARTESIA
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar an AND ABANDONED. Spud Date. Rig Release Date.	R/JB to 589°. RIH open ended to 1280°. with 2% CaCl. WOC. Tagged at 640°. oped out casing. d cut off anchors. WELL IS PLUGGED OCT 13 2011 NMOCD ARTESIA
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and AND ABANDONED. Spud Date. Rig Release Date.	PR/JB to 589'. RIH open ended to 1280'. With 2% CaCl. WOC. Tagged at 640'. Sped out casing. Id cut off anchors. WELL IS PLUGGED OCT 13 2011 NMOCD ARTESIA Ge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and AND ABANDONED. Spud Date. Rig Release Date.	R/JB to 589°. RIH open ended to 1280°. with 2% CaCl. WOC. Tagged at 640°. oped out casing. d cut off anchors. WELL IS PLUGGED OCT 13 2011 NMOCD ARTESIA
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and AND ABANDONED. Spud Date. Rig Release Date. Title Regulatory Compliance. Type or print name. Tina Huerta E-mail address: tinah@watespetroleu.	PHONE: 575-748-4168
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and AND ABANDONED. Spud Date. Rig Release Date. Title Regulatory Compliance. Type or print name	R/JB to 589'. RIH open ended to 1280'. with 2% CaCl. WOC. Tagged at 640'. oped out casing. d cut off anchors. WELL IS PLUGGED RECEIVED OCT 13 2011 NMOCD ARTESIA ge and belief. Be Supervisor DATE October 12, 2011
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and AND ABANDONED. Spud Date. Rig Release Date. Title Regulatory Compliance. Title Regulatory Compliance. Title Regulatory Compliance. Type or print name Tina Huerta E-mail address: tinah@vatespetroleu Approved for plusging of well Ltability under brond is retained of C103 (Subsequent Report of C103 (Subsequ	PRICEIVED OCT 13 2011 NMOCD ARTESIA Results of supervisor DATE October 12, 2011 October 13, 2011 October 14, 2011 October 15, 2011 October 16, 2011 October 17, 2011 October 18, 2011 October 19, 2011
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 10/6/11 – MIRU. 10/7/11 – NU BOP. RIH to 1280' and pumped 100 bbls fresh water, no load. RIH with GPumped 100 sx Class "C" Neat cement. 10/10/11 – RIH to 1280', no tag. Would not load. Pumped 100 sx Class "C" Neat cement Pressured to 500 psi. Pumped 65 sx Class "C" Neat cement and circulated to surface. Top 10/11/11 – Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar and AND ABANDONED. Spud Date. Rig Release Date. Title Regulatory Compliance. Type or print name	PRICEIVED OCT 13 2011 NMOCD ARTESIA Results of Well-Plugging) Och Fage under ORALL MOC. Tagged at 640'. WELL IS PLUGGED OCT 13 2011 NMOCD ARTESIA October 12, 2011