<u>District I</u> 1625 N. French Dr , Hobbs, NM 88240 District III
1301 W: Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

MAY 2 2 2012

RECEIVED

Energy Minerals and Natural Resources

NMOCD ARTESIA propriate District Office in accordance with 19.15.29 NMAC

Santa Fe. NM 87505

Santa 1 C, 1414 0,7505													
Release Notification and Corrective Action													
nMUB 1215853411						OPERATOR Initial				al Report	П	Final Repor	
Name of Company: Linn Operating 269324						Contact: Joe							
Address: 2130 W. Bender Hobbs, NM 88240						Telephone No.: 575-738-1739							
Facility Name: Skelly Satelite #3 / Skelly #65						Facility Type: Satelite							
Surface Owner: Federal Mineral Owner:						: Federal			API No.: 3001505342				
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
G 21 17S 31E 2080				Non	North			East	Eddy		iy		
	J		L		L								
Latitude: 32N 49' 17" / pulled 32N 49' 16.8" Longitude: 103W 52' 21.9" / 103W 52' 23.1"													
NATURE OF RELEASE													
Type of Release: Oil / Produced Water							Volume of Release: 30 / 25 Volume Recovered: 22 / 18						
Source of Release: Steel pipeline						Date and Hour of Occurrence: O5/19/2012 8:30am Date and Hour of Discovery: O5/19/2012 9am						y:	
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? M. Bratcher - NM OCD / Terry Gregston- BLM						
By Whom? Joe Hernandez						Date and Hour 5/21/2012 8am							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
☐ Yes ⊠ No													
If a Watercou	irse was Im	pacted, Descri	ibe Fully.*	•		- L							
											_		
Describe Cau	se of Proble	em and Remed	dial Action	1 Taken. *: Compt	essor v	vent down on i	eset which caused	d the sp	eparator to	fill up. The	fluid	had no where	
Describe Cause of Problem and Remedial Action Taken.*: Compressor went down on reset which caused the speparator to fill up. The fluid had no where to go and with the compressor not getting rid of the gas the header pressured up and found a weak point on a repair clamp that was on a t.a. line on the													
header. Fluid started coming out of repair clamp.													
Describe Are	a Affected a	and Cleanup A	Action Tak	en.* : Recovered	40 bbl	s. Further rem	edial action pendi	ng					
				is true and compl									
			-	d/or file certain re e of a C-141 repo						_	-	T	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state,	or local law	/s and/or regu	lations.		г								
		#[ريد سيري			OIL CONSERVATION DIVISION							
Signature:	wife som free	Carriery	The same of the sa										
ممرية		time				Approved by District Supervisor:							
Printed Name: Joe Hernandez							LIAL						
Title: Production Foreman						Approval Date: Expiration Date:							
E-mail Address: jhernandez@linnenergy.com						Conditions of Approval:			Attached				

* Attach Additional Sheets If Necessary

Phone: 575-942-9492

Date: 05/22/2012

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION

2RP-1154