


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW1219431677 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Northwest Central Tank Battery	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	Lease No. (API#) 30-015-20972 McIntyre Federal #6 - Closest well

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	17	17S	30E					Eddy

Latitude 32 49.817 Longitude 103 59.765

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	700bbls oil 100bbls produced water	Volume Recovered	650bbls oil 50bbls produced water
Source of Release	10,000bbl open top tank	Date and Hour of Occurrence	06/25/2012	Date and Hour of Discovery	06/25/2012 9:52 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD Jim Amos-BLM Terry Gregston-BLM		
By Whom?	Michelle Mullins	Date and Hour	06/26/2012 10 02 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

10,000 bbl open top tank at the Northwest Central Tank Battery overflowed due to water being diverted to open top instead of tank battery; Along with an electrical error on alarm system. The valve has been changed to divert water to the correct Northwest Central tanks and the electrical issue has been corrected.

Describe Area Affected and Cleanup Action Taken.*

Initially 800bbls of fluid were released from the open top water tank and we were able to recover 700bbls with a vacuum truck. The entire spill was contained on the pad location surrounding the tank and measured an area of roughly 125' x 200'. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD / BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Josh Russo	Approved by District Supervisor: Signed By	
Title: HSE Coordinator	Approval Date: JUL 12 2012	Expiration Date:
E-mail Address: jrusso@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/29/2012 Phone: 432-212-2399	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION	

* Attach Additional Sheets If Necessary

PROF LN 2 LATER THAN:

2RP-1212