Form 3160-5 (August 2007)						•.
· · · · · · · · · · · · · · · · · · ·	UNITED STAT EPARTMENT OF THE		RECE OCD Artes			APPROVED 0. 1004-0135
	BUREAU OF LAND MAN			3 2013 -		July 31, 2010
SUNDRY	NOTICES AND REP	ORTS ON WELL	0	ŀ	NIMANIME 2210	
Do not use th abandoned we	is form for proposals ell. Use form 3160-3 (A	to drill or to re-en PD) for such pro	Rigiocd	ARTESIA	55 If Indian, Allottee o	r Tribe Name
SUBMIT IN TRI	IPLICATE - Other instr	uctions on revers	e side.		7. If Unit or CA/Agree NMNM112743	ement, Name and/or No
1. Type of Well	hor				8. Well Name and No. WHITBREAD BFG FEDERAL COM 1	
 ☑ Oil Well □ Gas Well □ Ot 2. Name of Operator YATES PETROLEUM CORP. 	Contact:				9. API Well No. 30-015-33932	
3a. Address		3b. Phone No. (in	clude area code)		10: Field and Pool, or	Exploratory
105 SOUTH FOURTH STREI ARTESIA, NM 88210		Ph: 575-748-4168 Fx: 575-748-4585			WILDCAT; BONE SPRING	
4. Location of Well (Footage, Sec., 2		ion)			11. County or Parish,	
Sec 1 T22S R24E SWNW 19	980FNL 660FWL				EDDY COUNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES)	TO INDICATE NA	ATURE OF N	IOTICE, REI	PORT, OR OTHE	R DATA
TYPE OF SUBMISSION		TYPE OF ACTION				
Notice of Intent		Deepen			n (Start/Resume)	U Water Shut-Of
	Alter Casing			□ Reclamat		U Well Integrity
□ Subsequent Report	Casing Repair			Recomple		□ ^{Other}
□ Final Abandonment Notice	Change Plans	🕆 🛛 Plug an		Temporar		
	Convert to Injection	on 🗆 Plug Ba	ck .	U Water Dis	sposal	· · · ·
	i hians to hilld and aban	don this well as to	IOWS:			
 Yates Petroleum Corporation MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug inside an 	nt as needed. ot a 25 sx Class C cerns in the 7 inch casing at id outside casing. Pump ide and outside casing at is in the 7 inch casing at of outside casing. Pump	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and	-5800 ft. packer and t displace it d top. WOC to packer and tai displace it d	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480	rt. RECLAMATION rt. ATTAC	OF APPROV
 MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holes place a 110 sx plug inside an 	nt as needed. ot a 25 sx Class C cerns in the 7 inch casing at id outside casing. Pump ide and outside casing at is in the 7 inch casing at of outside casing. Pump	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and	-5800 ft. packer and t displace it d top. WOC to packer and tai displace it d	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480	ONDITIONS T. RECLAMATION ATTAC	OF APPROV
 MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi if necessary reset the plug. 	int as needed. ot a 25 sx Class C ceme s in the 7 inch casing at id outside casing. Pump ide and outside casing at is in the 7 inch casing at id outside casing. Pump ide and outside casing a	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and	-5800 ft. packer and t displace it d top. WOC to packer and tai displace it d	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480	ONDITIONS T. RECLAMATION ATTAC	OF APPROV
 MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi 	int as needed. ot a 25 sx Class C cerns is in the 7 inch casing at id outside casing. Pump ide and outside casing at id outside casing. Pump ide and outside casing at is true and correct. Electronic Submission	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and across surface cas	-5800 ft. packer and t displace it d top. WOC to packer and tai displace it d ng shoe. WC	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480 DC to tag plug	ONDITIONS ft. ft. ft. ft. ft. ft. ft. ft. ft. ft.	OF APPROV
 MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi if necessary reset the plug. 	int as needed. ot a 25 sx Class C cerns in the 7 inch casing at ide and outside casing. Pump ide and outside casing at ide and outside casing at ide and outside casing at is true and correct. Electronic Submission For YATES PET Committed to AFMSS	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and across surface cas	-5800 ft. packer and t displace it d top. WOC to packer and tai displace it d ng shoe. WC	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480 OC to tag plug C to tag plug	ONDITIONS ft. ft. ft. ft. ft. ft. ft. ft. ft. ft.	OF APPROV
 MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi if necessary reset the plug. 	int as needed. ot a 25 sx Class C cerns in the 7 inch casing at ide and outside casing. Pump ide and outside casing at ide and outside casing at ide and outside casing at is true and correct. Electronic Submission For YATES PET Committed to AFMSS	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and across surface cas #174258 verified by ROLEUM CORPOR	-5800 ft. packer and t displace it d top. WOC to packer and tai displace it d ng shoe. WC the BLM Well TION, sent to KURT SIMMOI	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480 OC to tag plug C to tag plug the Carlsbad NS on 01/04/2 PORTING S	ONDITIONS ft. RECLAMATION ATTAC J. System D13 ()	OF APPROV
 MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi if necessary reset the plug. 14. Thereby certify that the foregoing in Name (Printed/Typed). TINA HUL	int as needed. int a 25 sx Class C cerner is in the 7 inch casing at id outside casing. Pump ide and outside casing at id outside casing. Pump ide and outside casing at id outside casing. Submission For YATES PET Committed to AFMSS ERTA Submission)	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and across surface cas #174258 verified by ROLEUM CORPOR 5 for processing by Ti	-5800 ft. packer and t displace it d top. WOC to packer and tai displace it d ng shoe. WC the BLM Well TION, sent to KURT SIMMOI the REG RE atte 12/31/20	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480 DC to tag plug C to tag plug I Information 5 othe Carlsbad NS on 01/04/2 PORTING S	ONDITIONS ft. RECLAMATION ft. ATTAC 3, System D13 () UPERVISOR	OF APPROV
 MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi if necessary reset the plug. 14. Thereby certify that the foregoing i Name (<i>Printed/Typed</i>). TINA HUI Signature (Electronic	int as needed. int a 25 sx Class C cerner is in the 7 inch casing at id outside casing. Pump ide and outside casing at id outside casing. Pump ide and outside casing at id outside casing. Submission For YATES PET Committed to AFMSS ERTA Submission)	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and across surface cas #174258 verified by ROLEUM CORPOR 5 for processing by Ti Da FOR FEDERAL	-5800 ft. a packer and t displace it d b top. WOC to b top. WO	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480 DC to tag plug to the Carlsbad NS on 01/04/2 PORTING S D12 DFFICE USI	ONDITIONS ft. RECLAMATION ft. ATTAC 3, System D13 () UPERVISOR	OF APPROV PROCEDURE HED
 MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holes place a 110 sx plug inside an This will place 130 ft plug insi if necessary reset the plug. Thereby certify that the foregoing i Name (<i>Printed/Typed</i>). TINA HUI Signature (Electronic 	int as needed. int a 25 sx Class C cerner in the 7 inch casing at id outside casing. Pump ide and outside casing at id outside casing. Pump ide and outside casing at id outside casing. Pump ide and outside casing at is true and correct. Electronic Submission For YATES PET Committed to AFMSS ERTA Submission) THIS SPACE I a Approval of this notice d puitable title to those rights in	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and across surface cas #174258 verified by ROLEUM CORPOR 5 for processing by Ti Da FOR FEDERAL O	-5800 ft. packer and t displace it do top. WOC to packer and tai displace it do ng shoe. WC the BLM Well ATION, sent to KURT SIMMOI the REG RE the 12/31/20 DR STATE C ittle SE	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480 DC to tag plug I Information to the Carlsbad NS on 01/04/2 PORTING S	ONDITIONS ft. RECLAMATION ft. ATTAC 3, System D13 () UPERVISOR	OF APPROV
 MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holess place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holess place a 110 sx plug inside an This will place 130 ft plug inside an This will place 130 ft plug inside if necessary reset the plug. Thereby certify that the foregoing in Name (<i>Printed/Typed</i>). TINA HULE Signature (Electronic Approved By Conditions of approvel, if any, are attach would entify the applicant holds legal or explicitly would entify the applicant to conditional set of the applicant to condit set of the applicant to conditional set of the ap	int as needed. int a 25 sx Class C cerner is in the 7 inch casing at ide and outside casing a ide and outside casing at ide and outside casing at ide and outside casing at ide and outside casing at is true and correct. Electronic Submission For YATES PET Committed to AFMSS ERTA Submission) THIS SPACE I a Approval of this notice d putable title to those rights in het operations thereon. 3 U.S.C. Section 1212, make	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and across surface cas #174258 verified by ROLEUM CORPOR 5 for processing by Ti Da FOR FEDERAL O oes not warrant or the subject lease it a crime for any perso	-5800 ft. a packer and t displace it do backer and tail displace it do backer and tail displace it do ng shoe. WC the BLM Well ATION, sent to KURT SIMMOD de REG RE ate 12/31/20 DR STATE C ffice CCC n knowingly and	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480 OC to tag plug I Information o the Cartsbad NS on 01/04/2 PORTING S	ONDITIONS RECLAMATION ATTAC System D13 () UPERVISOR	OF APPROV
 MIRU any safety equipme Set a CIBP at 5800 ft. Sp Perforate 4 squeeze holess place a 110 sx plug inside an This will place 130 ft plug insi necessary reset the plug. Perforate 4 squeeze holess place a 110 sx plug inside an This will place 130 ft plug inside an This will place 130 ft plug inside an This will place 130 ft plug inside if necessary reset the plug. 14. Thereby certify that the foregoing i Name (<i>Printed/Typed</i>). TINA HUI Signature (Electronic 	int as needed. Not a 25 sx Class C cerner is in the 7 inch casing at ide and outside casing at is true and correct. Electronic Submission For YATES PET Committed to AFMSS ERTA Submission) THIS SPACE I a Approval of this notice d putable title to those rights in het operations thereon. 3 U.S.C. Section 1212, make	ent plug from 5660 3420 ft. TIH with a o a 110 sx plug and across Bone Spring 1610 ft. TIH with p o a 110 sx plug and across surface cas #174258 verified by ROLEUM CORPOR 5 for processing by Ti Da FOR FEDERAL O oes not warrant or the subject lease it a crime for any person a st o any matter within	-5800 ft. a packer and the displace it do backer and tail displace it do backer and tail displace it do ng shoe. WC the BLM Well ATION, sent to KURT SIMMOD the REG RE ate 12/31/20 DR STATE C ffice CCC n knowingly and a tis jurisdiction.	C ail pipe to own to 3290 o tag plug, if I pipe to own to 1480 OC to tag plug I Information 1 o the Cartsbad NS on 01/04/2 PORTING S DFFICE USI	ONDITIONS ft. RECLAMATION ATTAC 5 System D13 () UPERVISOR E E	OF APPROV

•

Additional data for EC transaction #174258 that would not fit on the form

32. Additional remarks, continued

ι

5. Perforate 4 squeeze holes at 150 ft. Tie on to 7 inch casing establish circulation and spot 160 ft plug (50 sx) from 0-150 ft. WOC and tag.
 6. Cut off wellhead and install dry hole marker, clean up location as per regulated. Release equipment.

Wellbore schematics attached.



