Submit 3 Copies To Appropriate Distri	state o	of New Mexico	Form C-103
Office <u>District I</u>	Energy, Minera	ls and Natural Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO.	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-015-333670	
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> Santa Fe, NM 87505		STATE FEE 🔀	
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.
SUNDRY NO	TICES AND REPORT	S ON WELLS	7. Lease Name or Unit Agreement
(DO NOT USE THIS FORM FOR PRODUCTION OF THE PROPERTY OF THE PR			Name ROGERS
PROPOSALS.)  1. Type of Well:			8. Well Number
Oil Well Gas V	Well 🔯 Other		#1
2. Name of Operator	wen 🖂 Ouler	RECEIVEL	9. OGRID Number
CHI OPERATING, INC		SEP 3 0 2005	004378
3. Address of Operator			10. Pool name or Wildcat
P.O. BOX 1799 MIDLAN	JD TY 70702	OGD-AHTEDIA	Loving; Morrow, North
4. Well Location	ND, 1X, 79702		Loving, Morrow, North
1	920 fact from the S	OUTH line and 60	60' feet from the EAST line
Section 29		Range 27E	
Section 29		ow whether DR, RKB, RT	
	N POS. 3 (2.24)	ow whether DR, KKD, KI 3'- GR	, OK, etc.)
Pit or Below-grade Tank Application	920020MBVC		ed)
Pit Location: ULSectTv			
		ocation UL Sect Tw	
	nd feet from the		P,
KKK I OLI CILIIIK AI			
12. Che	INTENTION TO:		BSÉQUENT REPORT OF:
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON	INTENTION TO:  PLUG AND ABANDO  CHANGE PLANS	SUE REMEDIAL WOR	BSÉQUENT REPORT OF:
12. Che NOTICE OF PERFORM REMEDIAL WORK	INTENTION TO:  PLUG AND ABANDO  CHANGE PLANS	SUE REMEDIAL WOR	BSÉQUENT REPORT OF:  RK
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	INTENTION TO:  PLUG AND ABANDO  CHANGE PLANS  MULTIPLE	SUE REMEDIAL WOR COMMENCE DE CASING TEST A CEMENT JOB	BSÉQUENT REPORT OF: RK
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	INTENTION TO:  PLUG AND ABANDO  CHANGE PLANS  MULTIPLE COMPLETION	SUE REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER:	BSÉQUENT REPORT OF: RK
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or co	PLUG AND ABANDO  CHANGE PLANS  MULTIPLE COMPLETION  ompleted operations. (Clean	SUE REMEDIAL WOR COMMENCE DE CASING TEST A CEMENT JOB OTHER:	BSÉQUENT REPORT OF: RK
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or co of starting any proposed or recompletion.  4/12/05 RU PU. TIH tag @ 11,9	PLUG AND ABANDO  CHANGE PLANS  MULTIPLE COMPLETION  completed operations. (Clead work). SEE RULE 1103.	SUE REMEDIAL WOR  COMMENCE DE CASING TEST A CEMENT JOB OTHER: rly state all pertinent details, an For Multiple Completions: A csg t/2000#, circ hole clean w/2	ALTERING CASING ALTERING CASING ABANDONMENT  ABANDONMENT  ABOMPLETION  Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion  2% KCL wtr. Find PBTD @ 11,935', TOC @
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or co of starting any proposed or recompletion.  4/12/05 RU PU. TIH tag @ 11,9 5350', Perf 11,879-882', 11,871-	CHANGE PLANS  CHANGE PLANS  MULTIPLE COMPLETION  Completed operations. (Clead work). SEE RULE 1103.  17', drill out t/11,935', tst c-876'. Set pkr @ 11,802'.	SUE REMEDIAL WOR  COMMENCE DE CASING TEST A CEMENT JOB OTHER: rly state all pertinent details, an For Multiple Completions: A csg t/2000#, circ hole clean w/2 TIH & set CIBP @ 11,865', P.	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT AB
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or co of starting any proposed or recompletion. 4/12/05 RU PU. TIH tag @ 11,9 5350', Perf 11,879-882', 11,871- Tree, tst csg t/1500#-all ok, RU I	CHANGE PLANS  CHANGE PLANS  MULTIPLE COMPLETION  Completed operations. (Clead work). SEE RULE 1103.  Plant dill out t/11,935', tst of -876'. Set pkr @ 11,802'. The complete of the complete operations.	SUE REMEDIAL WOR  COMMENCE DE CASING TEST A CEMENT JOB OTHER: rly state all pertinent details, an For Multiple Completions: A csg t/2000#, circ hole clean w/2 TIH & set CIBP @ 11,865', P.	ALTERING CASING ALTERING CASING ABANDONMENT  ABANDONMENT  ABOMPLETION  Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion  2% KCL wtr. Find PBTD @ 11,935', TOC @
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or co of starting any proposed or recompletion.  4/12/05 RU PU. TIH tag @ 11,9 5350', Perf 11,879-882', 11,871-	CHANGE PLANS  CHANGE PLANS  MULTIPLE COMPLETION  Completed operations. (Clead work). SEE RULE 1103.  Plant dill out t/11,935', tst of -876'. Set pkr @ 11,802'. The complete of the complete operations.	SUE REMEDIAL WOR  COMMENCE DE CASING TEST A CEMENT JOB OTHER: rly state all pertinent details, an For Multiple Completions: A csg t/2000#, circ hole clean w/2 TIH & set CIBP @ 11,865', P.	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT AB
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or co of starting any proposed or recompletion.  4/12/05 RU PU. TIH tag @ 11,9 5350', Perf 11,879-882', 11,871- Tree, tst csg t/1500#-all ok, RU 16 6pm put down sales line on 14/6-	CHANGE PLANS  CHANGE PLANS  MULTIPLE COMPLETION  COMPL	SUE REMEDIAL WOR  COMMENCE DE CASING TEST A CEMENT JOB OTHER:  rly state all pertinent details, an For Multiple Completions: A csg t/2000#, circ hole clean w/2 TIH & set CIBP @ 11,865', Paguns. Clean up t/pit in 4hrs, flw	ALTERING CASING ALTERING CASING ABANDONMENT  BY  ABANDONMENT  ABANDONMENT  ABANDONMENT  BY  ABANDONMENT  ABANDONMENT  BY  BY  BY  BY  BY  BY  BY  BY  BY  B
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or co of starting any proposed or recompletion.  4/12/05 RU PU. TIH tag @ 11,9 5350', Perf 11,879-882', 11,871- Tree, tst csg t/1500#-all ok, RU 1 6pm put down sales line on 14/6- I hereby certify that the infe	CHANGE PLANS  CHANGE PLANS  MULTIPLE COMPLETION  COMPL	SUE REMEDIAL WOR  COMMENCE DE CASING TEST A CEMENT JOB OTHER:  rly state all pertinent details, an For Multiple Completions: A csg t/2000#, circ hole clean w/2 TIH & set CIBP @ 11,865', Peruns. Clean up t/pit in 4hrs, flw  and complete to the best of	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT AB
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or confector of starting any proposed or recompletion. 4/12/05 RU PU. TIH tag @ 11,9 5350', Perf 11,879-882', 11,871- Tree, tst csg t/1500#-all ok, RU I 6pm put down sales line on 14/6 I hereby certify that the infecertify that any pit or below-grade tan alternative OCD-approved plan II.  SIGNATURE	PLUG AND ABANDO  CHANGE PLANS  MULTIPLE COMPLETION  Ompleted operations. (Clead work). SEE RULE 1103.  17', drill out t/11,935', tst of -876'. Set pkr @ 11,802'. The second will be constructed on the has been/will be constructed on the has been been been been been been been bee	SUE REMEDIAL WOR  COMMENCE DE CASING TEST A CEMENT JOB OTHER:  rly state all pertinent details, an For Multiple Completions: A csg t/2000#, circ hole clean w/2 TIH & set CIBP @ 11,865', Peruns. Clean up t/pit in 4hrs, flw  and complete to the best of	ALTERING CASING ALTERING CASIN
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or confector of starting any proposed or recompletion. 4/12/05 RU PU. TIH tag @ 11,9 5350', Perf 11,879-882', 11,871- Tree, tst csg t/1500#-all ok, RU I 6pm put down sales line on 14/6 I hereby certify that the infecertify that any pit or below-grade tan alternative OCD-approved plan II.  SIGNATURE	CHANGE PLANS  CHANGE PLANS  MULTIPLE COMPLETION  COMPL	COMMENCE DE CASING TEST A CEMENT JOB  OTHER:  rly state all pertinent details, at For Multiple Completions: A Casg t/2000#, circ hole clean w/2 TIH & set CIBP @ 11,865', Pouns. Clean up t/pit in 4hrs, flw and complete to the best or closed according to NMOCD guident.	ALTERING CASING ALTERING CASING ABANDONMENT  BY CLETTICK  ABANDONMENT  ABANDONMENT  ABANDONMENT  BY CLETTICK  ABANDONMENT  ABANDONMENT  ABANDONMENT  BY CLETTICK  ABANDONMENT  BY CLETTICK  ABANDONMENT  BY CLETTICK  ABANDONMENT  BY CLETTICK
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or confector of starting any proposed or recompletion. 4/12/05 RU PU. TIH tag @ 11,9 5350', Perf 11,879-882', 11,871- Tree, tst csg t/1500#-all ok, RU I 6pm put down sales line on 14/6 I hereby certify that the infecertify that any pit or below-grade tan alternative OCD-approved plan II.  SIGNATURE	PLUG AND ABANDO  CHANGE PLANS  MULTIPLE COMPLETION  Ompleted operations. (Clead work). SEE RULE 1103.  17', drill out t/11,935', tst of -876'. Set pkr @ 11,802'. The second will be constructed on the has been/will be constructed on the has been been been been been been been bee	SUE REMEDIAL WOR  COMMENCE DE CASING TEST A CEMENT JOB OTHER:  rly state all pertinent details, ar For Multiple Completions: A csg t/2000#, circ hole clean w/2 TIH & set CIBP @ 11,865', P. guns. Clean up t/pit in 4hrs, flw  and complete to the best or closed according to NMOCD guide  TITLE Regulatory	ALTERING CASING ALTERING CASING ABANDONMENT  BY CLETTICK  ABANDONMENT  ABANDONMENT  ABANDONMENT  BY CLETTICK  ABANDONMENT  ABANDONMENT  ABANDONMENT  BY CLETTICK  ABANDONMENT  BY CLETTICK  ABANDONMENT  BY CLETTICK  ABANDONMENT  BY CLETTICK
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or consistent of starting any proposed or recompletion. 4/12/05 RU PU. TIH tag @ 11,95350', Perf 11,879-882', 11,871-17ee, tst csg t/1500#-all ok, RU 16pm put down sales line on 14/6  I hereby certify that the infectify that any pit or below-grade tan alternative OCD-approved plan III.  SIGNATURE Type or print name Robi  (This space for State use)  APPPROVEROR RECOF	PLUG AND ABANDO  CHANGE PLANS  MULTIPLE COMPLETION  Ompleted operations. (Clead work). SEE RULE 1103.  17', drill out t/11,935', tst of -876'. Set pkr @ 11,802'. The set of the	SUE REMEDIAL WOR  COMMENCE DE CASING TEST A CEMENT JOB OTHER:  rly state all pertinent details, ar For Multiple Completions: A csg t/2000#, circ hole clean w/2 TIH & set CIBP @ 11,865', P. guns. Clean up t/pit in 4hrs, flw  and complete to the best or closed according to NMOCD guide  TITLE Regulatory	ALTERING CASING ALTERING CASING ABANDONMENT  BY CLETTICK  ABANDONMENT  ABANDONMENT  ABANDONMENT  BY CLETTICK  ABANDONMENT  ABANDONMENT  ABANDONMENT  BY CLETTICK  ABANDONMENT  BY CLETTICK  ABANDONMENT  BY CLETTICK  ABANDONMENT  BY CLETTICK
12. Che NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or confector of starting any proposed or recompletion. 4/12/05 RU PU. TIH tag @ 11,9 5350', Perf 11,879-882', 11,871- Tree, tst csg t/1500#-all ok, RU 16pm put down sales line on 14/6 I hereby certify that the infecertify that any pit or below-grade tan alternative OCD-approved plan II.  SIGNATURE Type or print name Robi  (This space for State use)	PLUG AND ABANDO  CHANGE PLANS  MULTIPLE COMPLETION  Completed operations. (Clead work). SEE RULE 1103.  Plant (11,935), tst of 1,802'. The completed will be constructed on the constructed of the construc	SUE REMEDIAL WOR  COMMENCE DE CASING TEST A CEMENT JOB OTHER:  rly state all pertinent details, ar For Multiple Completions: A csg t/2000#, circ hole clean w/2 TIH & set CIBP @ 11,865', P. guns. Clean up t/pit in 4hrs, flw  and complete to the best or closed according to NMOCD guide  TITLE Regulatory	ALTERING CASING ALTERING CASING ABANDONMENT ABANDONMEN