Form C-103 Submit 1 Copy To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources Revised August 1, 2011 District 1 - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-015-03169 District II - (575) 748-1283 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III - (505) 334-6178 STATE 😠 FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV - (505) 476-3460 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM B-514 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A G.J. WEST COOP UNIT DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well X Gas Well Other #016 2. Name of Operator 9. OGRID Number COG OPERATING LLC 229137 3. Address of Operator 10. Pool name or Wildcat 600 W. ILLINOIS AVE., MIDLAND, TEXAS 79701 GJ: 7RVS-ON-GB-GLORIETA-YESO. 4. Well Location 1650 Unit Letter feet from the line and 330 feet from the line Section 28 Township 17S Range 29E **NMPM** County EDDY 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,556' - GR 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING CHANGE PLANS **TEMPORARILY ABANDON** COMMENCE DRILLING OPNS. P AND A **PULL OR ALTER CASING** MULTIPLE COMPL CASING/CEMENT JOB RECEIVED DOWNHOLE COMMINGLE FEB **25** 2013 OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC.. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1) SET 4-1/2" CIBP @ 4,000'; PUMP 35 SXS.CMT. @ 4,000'-3,650' (DV TOOL); CIRC. WELL W/ PXA MUD. 2) PUMP 25 SXS.CMT. @ 2,800'-2,600' (T/S.A. X 7"CSG.SHOE); WOC X TAG CMT. PLUG. 3) CUT X PULL 4-1/2" CSG. @ +/-2,200'. 4) PUMP 50 SXS.CMT. @ 2,250'-2,040'(4-1/2"CSG.CUT X B/ ANHY.); WOC X TAG CMT. PLUG. 5) PERF. 7" CSG. X ATTEMPT TO SQZ. 40 SXS.CMT. @ 515'-415'(T/ANHY. X B/SALT); WOC X TAG CMT. PLUG. 6) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 100 SXS.CMT. @ 330'-3'. 7) DIG OUT X OUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Approval Granted providing work is complete by may 31 - 20/3

E-mail address:

deyler@milagro-res.com

DATE.

PHONE 432.687.3033

**SIGNATURE** 

For State Use Only
APPROVED BY


Type or print name DAVID A.

Conditions of Approval (if any):

EYLER

GJ West COOP Unit #16 **Empire** Reservoir: Grayburg Jackson Field Well ID info: Location: Footage: 16505 FNL 330 FEL API No: 30-015-03169 Sec. 28 - T17S - R29E Spud Date: 11/25/1946 Section: Block: Survey: KB -County Eddy County, NM Surf Csg: Elevations: 3556' 8-5/8" 28# GL KB Set @: Cement w/ 281' 50 sxs KB Calc circ. History Top of cmt est @ 1500'. LS Csg: 7" 20# Set @ 2673 Cement w/ 100 sxs · circ. Top of cmt @ 2520', CBL. Current Tubing Detail (top to bottom) Joints Description Footage Depth 2-7/8" tbg SN 4932 157 4932 4933 Grayburg San Andres 2700 - 70', 210 holes, no results. Completed in Open Hole 2673 - 2823'. (Behind pipe) Acidized 6,050 gal 15% NEFE DV 3693' Rod Detail (top to bottom) Weatherford 320-213-120 **Pumping Unit** Paddock 4058-4816', 30 holes Description Footage Depth Acidized 4058 - 4441 w/1,000 gal 15% HCL 7/8" Rods 1875 1875 32,000 gal 20% HCL, 54,000 gal lg, 5000 gal 15% NEFE 3/4" Norris N97 Rods 2-1/2" x 1-1/2" x 16' RHBC HVR Pump PUMP IS STUCK 118 2950 4825 Paddock 4876-94' 20 holes Acidize w/1000 gal 15% NEFE Frac w/42,000 gal GW, 48,500 # sd 4841 1 16 4-1/2" 11.6# 5190 1st stage: 170 sxs. Premium Plu Prod Csg: Set @ Cement w/ 1st stage: 41 sxs (did not cer circ. , W. Goode 12/19/12 PTBD: 5190' Updated: SET 10/1994

TD: 5215'



## NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

## CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: COG				
Well Name & Number: 6J	West	Coop	Unit	#016
API#: 30-015-C	3169			

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.

10. Plugs may be combined after consulting with and getting approval from NMOCD.

11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 03/01/2013

APPROVED BY:

## GUIDELINES FOR PLUGGING AND ABANDONMENT

## DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000 is to be allowed between cement plugs in open hole and no more than 3000 in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - Fusselman
  - o Devonian
  - o Morrow
  - Wolfcamp
  - Bone Spring
  - Delaware
  - Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist be hind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).