


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

Please use API's when submitting

njmw130251448

Name of Company Chevron Delaware Basin <i>4323</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address PO Box 190, Hobbs, NM 88241		Contact Bradley Blevins		
Facility Name Culebra Bluff SWD Water Transfer Line		Telephone No. (575) 391-1462		
		Facility Type SWD		
Surface Owner	Mineral Owner	Lease No.		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	36	22S	28E					Eddy County, NM
<i>E</i>	<i>2</i>	<i>23S</i>	<i>28E</i>					

Latitude: N 32.34734° Longitude W 104.04839° *API 30-015-2275*

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 77 bbls	Volume Recovered 0 bbls
Source of Release Hole in 3" ball valve in the transition	Date and Hour of Occurrence 03/25/2013 @ 12:30 pm	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A hole in the 3" ball valve in the transition caused 77 bbls of produced water to leak onto the ground. No fluids were recovered and the valve was repaired.

Describe Area Affected and Cleanup Action Taken.*
The area affected us approximately 40' x 450'. A hole in the 3" ball valve in the transition caused 77 bbls of produced water to leak onto the ground. No fluids were recovered and the valve was repaired. Further remediation will be performed in accordance with a NMOCD-approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by District Supervisor:	
Title: EHS Specialist	Approval Date:	Expiration Date:
E-mail Address: Bradley.blevins@chk.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>4/3/13</i>	Phone: (575) 391-1462	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**
May 17, 2013

2RP-1619