District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr. WELL API NO. 30 015 27159 5. Indicate Type of Lease	1ay 27, 2004
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr. 30 015 27159 5. Indicate Type of Lease	
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr. 5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aziec, NVI 8/410	X
District IV Santa Fe, NW 87303 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement of the Property of the Pr	ent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Dagger Draw A	
PROPOSALS.)	
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator OCT 0 5 2005 9. OGRID Number 021355	
SOUTHWEST ROYALITES, INC.	
3. Address of Operator 10. Pool name or Wildcat	
6 DESTA DRIVE, STE 2100, MIDLAND, TEXAS 79705 DAGGER DRAW	
4. Well Location	1.
	line
Section 17 Township 19S Range 25E NMPM Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	County
3538.3' GL	
Pit or Below-grade Tank Application or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CA	ASING [
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
OTHER: RECOMPLETE IN WOLFCAMP FORMATION x OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including es	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	
	i completion
or recompletion.	1 completion
or recompletion.	i completioi
or recompletion. Planned procedure:	-
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap	-
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#.	pprox 7310'
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#. Perforate 6736' – 6808'. Trip in hole with treating packer on workstring and spot HCL acid. Set packer @ 6700' and acidize	pprox 7310'
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#.	pprox 7310'
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#. Perforate 6736' – 6808'. Trip in hole with treating packer on workstring and spot HCL acid. Set packer @ 6700' and acidize gals 20% NEFE HCL acid and BS.	pprox 7310'
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#. Perforate 6736' – 6808'. Trip in hole with treating packer on workstring and spot HCL acid. Set packer @ 6700' and acidize gals 20% NEFE HCL acid and BS.	pprox 7310'
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#. Perforate 6736' – 6808'. Trip in hole with treating packer on workstring and spot HCL acid. Set packer @ 6700' and acidize gals 20% NEFE HCL acid and BS.	pprox 7310'
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#. Perforate 6736' – 6808'. Trip in hole with treating packer on workstring and spot HCL acid. Set packer @ 6700' and acidize gals 20% NEFE HCL acid and BS.	pprox 7310'
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#. Perforate 6736' – 6808'. Trip in hole with treating packer on workstring and spot HCL acid. Set packer @ 6700' and acidize gals 20% NEFE HCL acid and BS.	oprox 7310' e w/10,000
Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#. Perforate 6736' – 6808'. Trip in hole with treating packer on workstring and spot HCL acid. Set packer @ 6700' and acidize gals 20% NEFE HCL acid and BS. Flow and swab back load. Trip out of hole with tubing and packer. Run production equipment and test well.	oprox 7310' e w/10,000
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#. Perforate 6736' – 6808'. Trip in hole with treating packer on workstring and spot HCL acid. Set packer @ 6700' and acidize gals 20% NEFE HCL acid and BS. Flow and swab back load. Trip out of hole with tubing and packer. Run production equipment and test well. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-appro	oprox 7310' e w/10,000 / pit or below- oved plan .
or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#. Perforate 6736' – 6808'. Trip in hole with treating packer on workstring and spot HCL acid. Set packer @ 6700' and acidize als 20% NEFE HCL acid and BS. Flow and swab back load. Trip out of hole with tubing and packer. Run production equipment and test well. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any trade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-appro SIGNATURE TITLE Operations Assistant DATE 10/3/05 Type or print name Dawn M. Howard E-mail address: dhoward@claytonwilliams.com Telephone No. 432/688-3267	oprox 7310' e w/10,000 v pit or below- ved plan □.
Or recompletion. Planned procedure: Move in and rig up pulling unit. Nipple up and test BOP pulling tubing. Trip in hole with bit and scraper and cleanout to ap and TIH. Set CIBP @ 7300' and cap with 20' cement. Test casing to 1000#. Perforate 6736' – 6808'. Trip in hole with treating packer on workstring and spot HCL acid. Set packer @ 6700' and acidize als 20% NEFE HCL acid and BS. Flow and swab back load. Trip out of hole with tubing and packer. Run production equipment and test well. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any trade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-appro SIGNATURE Type or print name Dawn M. Howard E-mail address: dhoward@claytonwilliams.com Telephone No. 432/688-3267	oprox 7310' e w/10,000 / pit or below- oved plan □.