


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC

**Release Notification and Corrective Action**

*nJW* 1323837931 OPERATOR  Initial Report  Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: HE West B #4 Battery- West B 38	Facility Type: Battery
Surface Owner: Federal	Mineral Owner:
API No.: 3001526001	

**LOCATION OF RELEASE**

Unit Letter F	Section 10	Township 17S	Range 31E	Feet from the 2085	North/South Line North	Feet from the 1980	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.850600037686 Longitude: -103.859729591584

**NATURE OF RELEASE**

Type of Release: Produced Water / Oil	Volume of Release: 5 gal / 5 gal	Volume Recovered: 0 / 0
Source of Release: Poly Pipeline	Date and Hour of Occurrence: 08/16/2013 7:00pm	Date and Hour of Discovery: 08/16/2013 7:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM	
By Whom? Brian Wall	Date and Hour 08/19/2013 2:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Flowline from West B 41 had developed a pin hole going to the West B#4 Tank Battery on South side of the battery. Possible cause fatigue. Line was repaired.		
Describe Area Affected and Cleanup Action Taken.* : A light spray of fluid developed. Area affected was 3 x 4 ft		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brian Wall</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Brian Wall	Approved by District Supervisor:	Signed By <i>Mike Burton</i>
Title: Construction Foreman II	Approval Date: <b>AUG 26 2013</b>	Expiration Date:
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/20/13 Phone: 806-367-0645	Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

**Sept. 26, 2013**

*2RP-1864*