
Office	State of New Mex			Form C	
<u>District 1</u> – (575) 393-6161	Energy, Minerals and Natura	ıl Resources		Revised August 1	, 2011
1625 N. French Dr., Hobbs, NM 88240		l l	VELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION I	11 V I N I I N I	30-015-03028		
<u>District III</u> – (505) 334-6178	1220 South St. Franc	1.5	5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410			STATE X		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 875	' "	. State Oil & Gas 3-1266	Lease No.	
87505 SUNDRY NOTIC	CES AND REPORTS ON WELLS	7	. Lease Name or	Unit Agreement Na	ıme
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA		CHOH	GJ WEST COOP	UNIT	
PROPOSALS.) 1. Type of Well: Oil Well X G	as Well Other	•	. Well Number		
2. Name of Operator			. OGRID Numbe	r	
COG OPERATING LLC			29137		
3. Address of Operator			10. Pool name or Wildcat		
600 W. ILLINOIS AVE., MIDLAN	D, TEXAS 79701		GRAYBURG-JAC	CKSON;QN-GB-SA	
4. Well Location					
Unit Letter; P; 330	o feet from the SOUTH line	and 330 feet fr	om the EAST	line	
Section 21	Township 17S	Range 29E	NMPM	EDDY County	/
	11. Elevation (Show whether DR, I	RKB, RT, GR, etc.)			
	3,547' - G	R			
12. Check A	ppropriate Box to Indicate Na	ture of Notice, Re	eport or Other l	Oata	
NOTICE OF INT	TENTION TO:	SURSE	EQUENT REF	ORT OF	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON X REMEDIAL WORK				ALTERING CASING	: I
TEMPORARILY ABANDON		COMMENCE DRILL		P AND A	,
PULL OR ALTER CASING		CASING/CEMENT J		I AND A	
DOWNHOLE COMMINGLE	MOLTIFLE COMPL	CASING/CEMENT J	ОВ Ц	•	
DOWN TOLL COMMINGEL					
OTHER:		OTHER:			
	eted operations. (Clearly state all pe	rtinent details, and g	ive pertinent date:	s, including estimate	ed date
	k). SEE RULE 19.15.7.14 NMAC.				
	PUMP 25 SXS. CMT. @ 3,950'-3,				
	400'-3,150' (7"CSG.SHOE, T/S.A.)	; WOC X TAG CMT	r. PLUG.		
3) PUMP 25 SXS. CMT. @ 2,0					
) SXS. CMT. @ 700'-3' (T/YATES,				
5) DIG OUT X CUT OFF WEI	LLHEAD 3' B.G.L.; WELD ON ST	EEL PLATE TO CS	GS. X INSTALL	DRY HOLE MARI	KER.
DURING THIS PROCEDURE WE P	PLAN TO USE THE CLOSED-LOC	P SYSTEM W/ A S	TEEL TANK AN	D HAUL CONTEN	JETS
TO THE REQUIRED DISPOSAL, P.		or or or Ellin with to	TEEE TANK A	D TIMOL CONTE	VL I U
CONDITIONS OF APPROVAL ATTACHI	ED Approved for plugging of	well bore only.	HE	CEIVED	
	Liability under bond is re	etained pending receipt			
Approval Granted providing work	in Of Calo3 (Subsequent Re	port of Well Plugging)	NU'	7 0 7 2013	
Completed by	which is skip and and	CD Web Page under			
Nov 12, 2014	Forms, www.cmnrd.state	.nm.jus/oca.	NMOC	D ARTESIA	
			ж		
I hereby certify that the information a	bove is true and complete to the bes	t of my knowledge a	nd belief.		
~ .					
SIGNATURE SIGNATURE	TITLE: AGEN	Т	DAT	TE: 11/05/13	
Type or print name: DAVID A. EYL For State Use Only	E-mail address: DEYI	LER@MILAGRO-R	ES.COM PHC	NE: 432.687.3033	
	n n	AC. M. M.		. 1.21	
APPROVED BY: Conditions of Approval (if any):	TITLE DIST &	Leywise)	DA	TE /1/12/2013	
See Attached COA's	•				
CETIME CONT					

COG Operating LLC



COG Operating LLC

Lease & Well # GJ West COOP Unit #24 P-21-175-29E 30-015-03028 330 FSL X 330 FEL Spud-5/4/61 Elevation - 3547' KB -CIRC. 80 SXS. CMT- @ 700'- 2' 8 5/8" 24# @ 270', cmt w/ 50 sx. Pump 25 SKS. CMT. @ 2090-1970' PAA MUD Pump 30 5x5, cms.@ 3400'-3150'- TAG Pump 25 SKS. CMT. @ 3950'- 3750! Marker it 3590' Paddock: SET 41/2" OIBP @ 3950! 4000 - 4388 29 holes ► DV tool @ 3785' Acidized w/2000 gal 15% NEFE 32,000 gal 20% HCL, 54,000 gal lg, 5000 gal 15% NEFE **Downhole Summary** ~15' of 2-7/8" mud joint regular collars Top of stuck mud joint ~4,441' 1st stage: 100sx. 50/50 CPOZ, w/2.5#salt, 4/10% Halad-9 EOT 4,456' Circ. 25 sx to surf. 2nd stage: 225 sx.'HOWCO LITE w/6# flocele, tail 55sx. 50/50 CPOZ w/2.5# salt, 4/10 Hal-9, circ 4 1/2" 11.6# @ 4614'. PBTD 4,469"

25 sk plug, 4765-4905

25 sk plug, 6062-6202

25 sk plug, 7238-7378 **TD 6 1/8" hole @ 7407'**

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: COG		_
Well Name & Number: 6 J West	Coop Unit	#24
api #: <u>30-015-03038</u>		-

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 11/12/2013

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).