Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
<u>District I-</u> (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Elicity, Minerals and Natural Resources	WELL API NO.
<u>District II</u> - (575) 748-1283 1301 W. Grand Ave., Artesia, NM 8821 0	OIL CONSERVATION DIVISION	30-015-21145 5. Indicate Type of Lease
District III- (505) 334-6178 1 000 Rio Brazos Rd., Aztec, NM 8741 0	1220 South St. Francis Dr.	STATE FEE S
District IV- (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		Fee
	CICES AND REPORTS ON WELLS DISSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR, USE "APPLI PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FOR SUCH	Otis SWD ~ 40334>
1. Type of Well: Oil Well	Gas Well Other SWD	8. Well Number 1
2. Name of Operator Mack	Energy Corporation	9. OGRID Number 013837
3. Address of Operator		SWD? Del Name, Middle atsimpson,
	60 Artesia, NM 88210	Ellenburger $\angle 97775$
4. Well Location Unit Letter J 1947 feet from the South line and 1971 feet from the East line		
Unit Letter J Section 4	Township 23S Range 27E	NMPM County Eddy
Section	11. Elevation (Show whether DR, RKB, RT, GR etc.	
	3131'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF I	NTENTION TO: SUI	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON	· · · · · · · · · · · · · · · · · · ·	RILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL CASING/CEME	NI JOB
CLOSED-LOOP SYSTEM	D D	·
OTHER:	Re-Entry OTHER:	nd give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion		
Or recompletion. Mack Energy proposes to do the following re-entry procedure.		
	g re-entry procedure.	·
1. MIRU PU, NU BOP 2. PU 6 1/8" bit. 10 DCS.		
3. Drill out cmt plugs @ surface, 325', 1030', 1700', 5280'. Test Csg to 1500#		
4. Drill out CIBP @ 6285'. Test perfs @ 6314' to 1000psi. If perfs do not hold pressure will need to squeeze perfs w/ 100sx class H 5. Drill out cmt plugs @ 8827'. Test squeezed perfs @ 10170' to 1000#		
6. Drill out cmt plug @ 10260', 10760'. Test esg to 1000# 7. Drill CIBP @ 11500'. Test perfs @ 11517' to 1000#. If perfs do not hold pressure will need to squeeze perfs w/ 100sx class H		
8. Finish drilling CIBP that was pushed to 11900' 9. Drill out cmt plug @ 11975'. Test perfs @ 12100' to 1000#. If perfs do not hold pressure will need to squeeze perfs w/ 100sx class H		
10. With Silver Oak Drilling rig. Drill out 7" csg shoe @ 12,234'		
11. Deepen well to geology called TD of12. Run 5" P-110 Flush Joint casing to TI	approximately 15,100' 🕜 D. DV tool placement will be picked off of log evaluation. Circ	culate cmt to surface RECEIVED
· · [JAN 15 2014
Spud Date:	Rig Release Date:	
	· · · · · · · · · · · · · · · · · · ·	NMOCD ARTESIA
I hereby certify that the information above is true slid complete to the best of my knowledge and belief.		
SIGNATURE DE LA VIANE TITLE Production Clerk DATE 1. (O.14		
Type or print name Deana Weave	E-mail address: dweaver@me	c.com PHONE: (575)748-1288
For State Use Only		
APPROVED BY: 1. U. Shapard TITLE "Geologist" DATE /-/5-2014 Conditions of Approval (if any):		