	UNITED STATES DEPARTMENT OF THE INTEXIOR BUREAU OF LAND MANAGEMENT			ја (КМ АРРЮУГД) ОХИИ Ко. 1903-6135 Гурнск Канси М. 2007		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or ro enter an				5. Lease Serial No LC 069465		
abandonud well. Use Form 3160-3 (APD) for such proposals.			6.	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7 If Unit of CA/Agreement, Name and/or No.		
Type of Well		······				
Oil Well Gas Well X. Giher						
Nordstrand Engineering inc				WEST HENSHAW PREMIER UT TR5		
a Address 3h Phone No <i>finclude arua coc</i>			(e) 3(30-015-03832		
		713-520-1555	5 10 Field and Pool, or Exploratory Area			
Location of Well (Footage, Sec , T , R	.M., OR Survey Description)					
NIT-U. 990 FT FORM THE	E S LINE, 330 FT , W-I	LINE, SEC- 3, T-16S, R/	ANGE-30E, E	DDY, NM		
	IECK APPROPRIATE I	BOX(ES) TO INDICATE I		NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION			TYPE OF #	CTION		
	Acadore	Uterneu	Pontazion Orian	(Resume)		Water Shin (Off
X Notice of linear	Mice Casing	having treat	Reviamanca			Well integrity
	Casing Repair	New Considerations	lievooplete	[Ullher
Subsequent Report	Chaoge Plans	19og and Absoration	feeporade Aba	ndant.		
Final Ab eithmusen: Songe	Concerto Justition	Play IV-S	With the provide			
1	L		L			***** ********************************
If the proposal is to deepen directionally or in Attach the Bond under which the work will following completion of the involved operative testing this twen comprised. Final Abanda determined that the site is ready for final wish	ocomplate nonzomally, give substitute he performed or provide the Bond No ons . If the operation results is a mut oment Noticos, shall be filed only afte	con file with BLM/BIA - Required substitution of recompletion or recompletion in a new rall requirements, including reclamation	chi deptits of all persinent ma equicht reports sthall, bei bler misterval, a Porm 3160 4, si E have been completed, and	ikers and zones Ewithin 30 days half be bled once the operator has		
Attach the Bond under which the work will following completion of the involved operati- testing in the tens completed 1. MOVE IN PLUGGING E 2. RIH AND TAG CIBP @ 3. RIH AND SET CIBP @ 4. PERF AND SET CIBP @ 5. PERF AND SET CIBP @ 5. PERF AND CIRCULATI 6. INSTALL PA MARKER-	ecomplete norizontally, give subsulta ta performed or provide the Gond No ones. If the optimion results is a mul- imment Notices shall be filed only after rection ? EQUIPMENT 2700' 2090' SPOT 25 SACK ACKS @ 450'-TAG E 35 SACKS TO SURI -CLEAN UP AND MO?	e brahons and measured and true vorte on file with BLM/BLA. Required subst vide completions on a na- e all requirements including reclamation S ON TOP * SQ2 cont from FACE FROM 60' (de VE OUT EQUIPMENT	cal depires of all periment in reacting reports shall be Mer winnerval, and the Mer winnerval, and b base or to have been completed, and to base or to 10 million to 11 mi	Hors and contes (within 30 days and to be the conce the operator thes - 340', we - 340', we conting s t-off V -5.	erity end t	rgs) -o surt.o
Attach the Bong under which the work will following completion of the involved operati- testing in the involved operati- testing in the involved operati- testing in the involved is ready for find with determined that the site is ready for find with 1. MOVE IN PLUGGING E 2. RIH AND TAG CIBP @ 3. RIH AND SET CIBP @ 4. PERF AND SET CIBP @ 4. PERF AND SET CIBP @ 5. PERF AND CIRCULATI 6. INSTALL PA MARKER- Steel pits will be used for Steel pits will be used for	ecomplete noncentality, give substitue ta performed or provide the Bond No one of the equation results in a mul- imment Nonces shall be filed only afte nection) EQUIPMENT 2700' 2090' SPOT 25 SACK ACKS @ 450'-TAG E 35 SACKS TO SURI CLEAN UP AND MO' ///// CLARED OND DO all fluids	e brahons and measured and true vorte on file with BLM/BLA. Required subst vide completions on a na- e all requirements including reclamation S ON TOP * SQ2 cont from FACE FROM 60' (de VE OUT EQUIPMENT	cal depires of all periment in reacting reports shall be Mer winnerval, and the Mer winnerval, and b base or to have been completed, and to base or to 10 million to 11 mi	Hors and contes (within 30 days and to be the conce the operator thes - 340', we - 340', we conting s t-off V -5.	woc Tag.	rgs) -o surt.o
Attach the Bond under which the work will leftering completion of the structured operati- testing ans tensormered. Frink Manada determined that the site is ready for fingl wisk 1. MOVE IN PLUGGING E 2. RIH AND TAG CIBP @ 3. RIH AND SET CIBP @ 4. PERF AND SET CIBP @ 4. PERF AND SET CIBP @ 5. PERF AND CIRCULATI 6. INSTALL PA MARKER- Steel pits will be used for	ecomplete noncentality, give substitue ta performed or provide the Bond No one of the equation results in a mul- imment Nonces shall be filed only afte nection) EQUIPMENT 2700' 2090' SPOT 25 SACK ACKS @ 450'-TAG E 35 SACKS TO SURI CLEAN UP AND MO' ///// CLARED OND DO all fluids	e brahons and measured and the work on file with BLM/BLA Required subs- bial completions on a na- e all requirements including reclamation S ON TOP * SQZ cont fre- FACE FROM 60' (de VE OUT EQUIPMENT	cal depires of all periment in reacting reports shall be Mer winnerval, and the Mer winnerval, and b base or to have been completed, and to base or to 10 million to 11 mi	Hors and contes (within 30 days and to be the conce the operator thes - 340', we - 340', we conting s t-off V -5.	woc Tag. hots, 2 cas: crify ent t	rgs) -o surf.
Attach the Bond under vilich the work will belowing completion of the involved operati- testing instructure completed 1. MOVE IN PLUGGING E 2. RIH AND TAG CIBP @ 3. RIH AND SET CIBP @ 4. PERF AND SET CIBP @ 4. PERF AND SET CIBP @ 5. NEERF AND CIRCULATI 6. INSTALL PA MARKER- Steel pits will be used for Thereby certify that the foregoing is read.	ecomplete noncontaily, give substitue ta performed or provide the Bond No one of the equilion robusts is a mul- imment Noncos shall be filed only alto nection) EQUIPMENT 2700' 2090' SPOT 25 SACK ACKS @ 450'-TAG E 35 SACKS TO SURI CLEAN UP AND MO' 	to be about and measured and the work on file with BLM/BA Required subs- bias completions on a na- e all requirements including reclamation S ON TOP * SQ2 cont fr- FACE FROM 60' (de VE OUT EQUIPMENT Title PRE	cal depits of all periment ma request spars shall be Mer wintering a shall be Mer wintering a shall be Mer wintering a shall be Mer be bese on 180 4 5 b Bese on t to 11 on 474' 22p percet * At cui annulue f Ground	Hors and contes (within 30 days and to be the conce the operator thes - 340', we - 340', we conting s t-off V -5.	woc Tag. hots, 2 cas: crify ent t	rgs) -o surt.
Attach the Bond under which the work will following completion of the involved operati- testing nas hear compresen- testing nas hear compresen- 2. RIH AND TAG CIBP @ 3. RIH AND SET CIBP @ 4. PERF AND SET CIBP @ 4. PERF AND SET CIBP @ 5. PERF AND CIRCULATI 6. INSTALL PA MARKER- Steel pits will be used for Thereby certify that the foregoing is Name: (Pinted/Typod)	ecomplete noncontaily, give substitue ta performed or provide the Bond No one of the equilion robusts is a mul- imment Noncos shall be filed only alto nection) EQUIPMENT 2700' 2090' SPOT 25 SACK ACKS @ 450'-TAG E 35 SACKS TO SURI CLEAN UP AND MO' 	to be about and measured and the works on the with BLMHA Required subst bigs completions in a net with requirements including reclamation S ON TOP # SQZ cost from FACE FROM 60' (de VE OUT EQUIPMENT This PRE	cal depits of all periment ins inducent reports shall be here inducent reports shall be here inducent a part 1960 + 3 is have been computated, and is how be	Hore and contes (within 30 days into the concent F Salt p - 340', we conting s t-otff V -S. (evel Dr	woc tag. hots, 2 cas: crify cost + y Hole Mark	rgs) -o surf.
Attach the Bong under which the work will following completion of the involved operati- testing ans been completed. Frind Manado determined that the site is ready for finder will 1. MOVE IN PLUGGING E 2. RIH AND TAG CIBP @ 3. RIH AND SET CIBP @ 4. PERF AND SET CIBP @ 4. PERF AND SPOT 25 S 5. PERF AND CIRCULATI 6. INSTALL PA MARKER- Steel pits will be used for Thereby certify that the foregoing is Name (Printed/Typed)	ecomplete noncentality, gives substitte to performed or provide the Bond No one of the equation results in a mul- ment Nonces shall be filled only alte nection) EQUIPMENT 2700' 2090' SPOT 25 SACK ACKS @ 450'-TAG E 35 SACKS TO SURF -CLEAN UP AND MO' IIIIY CT ARCOULT CT ARCOULT NOROS TRAND IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	e bratons and measured and the works i on file with BLM/BLA Required subs by a completion or a conservation of a de- r all requirements including reclamation S ON TOP # SQ2 cost from SQ2 cost from FACE FROM 60' (de- VE OUT EQUIPMENT Trite PRE Data 2-5	cal depits of all periment ins inducent reports shall be here inducent reports shall be here inducent a part 1960 + 3 is have been computated, and is how be	Hore and contes (within 30 days into the concent F Salt p - 340', we conting s t-otff V -S. (evel Dr	woc Tag. hots, 2 cas: crify ent t	rgs) -o surf.
Attach the Bong under which the work will belowing completion of the involved operati- testing in the involved operati- testing in the involved operati- testing in the involved is ready for final which determined that the site is ready for final which as RIH AND TAG CIBP @ 3. RIH AND SET CIBP @ 4. PERF AND SET CIBP @ 4. PERF AND SET CIBP @ 5. PERF AND SPOT 25 S 5. PERF AND CIRCULATI 6. INSTALL PA MARKER- Steel pits will be used for thereby certify that the foregoing is Name: (Printed/Typed) Steel pits will be used for Name: (Printed/Typed)	ecompeter noncontailing, gives substitute the performed or provide the Bond No one of the equilibrit scalar and inner Noncos shall be filed only after nection 1 EQUIPMENT 2700' 2090' SPOT 25 SACK ACKS @ 450'-TAG E 35 SACKS TO SURF -CLEAN UP AND MO' IIIIY CLEAN UP AND MO' IIIIIY CLEAN UP AND MO' IIIIY CLEAN UP AND MO' IIIIY CLEAN UP AND MO' IIIIIY CLEAN UP AND MO' IIIIY CLEAN UP AND MO' IIIIIY CLEAN UP AND MO' IIIIY CLEAN UP AND MO' IIIIIY CLEAN UP AND MO' IIIIIY CLEAN UP AND MO' IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	e is rations and measured and the work on file with BLM/BLA Required subs- ing the completions of a completion of a co- part completion of recompletions of a co- s all requirements including reclamation S ON TOP * S ON TOP 	cal depits of all period management in request reports shall be Mark without a farm 3160 a b b have been computed, and b base or ct to II on 474' 200 percet * At cut annulue f Ground f Ground 5-2014 LOR STATE OFFICE	Hors and contes (within 30 days and be hed once the operator has F Salt p IS', WB - 340', conting S t-off V -S. (evel) Dr USE	woc tag. hots, 2 cas: crify cost + y Hole Mark	rgs) -o surf.
Attach the Bong under which the work will biblewing completion of the involved operati- testing ans bene completed 1. MOVE IN PLUGGING E 2. RIH AND TAG CIBP @ 3. RIH AND SET CIBP @ 4. PERF AND SET CIBP @ 4. PERF AND SET CIBP @ 5. PERF AND CIRCULATI 6. INSTALL PA MARKER- Steel pits will be used for Thereby certify that the foregoing is Name (Protect/Typed) Signification of approval if any, are attac- midlions of approval if any are attac- midlions	ecomplete noricements, juva substitute ta performed or provide the Bond No- ment formed or provide the Bond No- ment formed or provide the Bond No- ment formed shall be filed only alto rection) EQUIPMENT 2700' 2090' SPOT 25 SACK ACKS @ 450'-TAG E 35 SACKS TO SURF -CLEAN UP AND MO' III/IY CLEAN UP AND MO' IIII/IY CLEAN UP AND MO' IIII/IY CLEAN UP AND MO' IIII/IY CLEAN UP AND MO' IIIIII CLEAN UP AND MO' IIIIII CLEAN UP AND MO' IIIIII IIIIII CLEAN UP AND MO' IIIIII CLEAN UP AND MO' IIIIII CLEAN UP AND MO' IIIIII CLEAN UP AND MO' IIIIIII IIIIIIIIIIIIIIIIIIIIIIIIIII	e bratons and measured and the work on file with BLM/BLA Required subst high completions or recompletions on a ner- e all requirements including reclamation S ON TOP * SQ2 cost for FACE FROM 60' (de VE OUT EQUIPMENT This PACE FOR FEDERAL Data 2- 3 THIS SPACE FOR FEDERAL So not warrant or the subject reaso unice crime for any person knowingly a	cal depits of all period management of an equilation reports shall be here without a form 1860 + s is have been computed, and be bese or the to 11 to	Hors and contes (within 30 days and be hed once the operator has F Salt p IS', with - 340', with conting S t-off V -S. (evel Dr USE Date	woc Tag. hots, Z cas: crity cost + y Hole Mark	rgs) -o surf.

SEE ATTACHED FOR CONDITIONS OF APPROVAL RECLAMATION PROCEDURE ATTACHED

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

۰.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

Requirements for ground level dry hole markers <u>Well Identification Markers</u> Conditions of Approval (COA)

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) Requires that ground level dry hole markers be placed on well within the Lesser Prairie Chicken habitat area. The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. An 8 inch X 8 inch steel plate 1/8 to 3/16 of an inch thick is to be placed on the old dry hole marker stand pipe 2 inches from ground level, in the Lesser Prairie Chicken habitat area.
- 2. Steel plate may be welded or bolted approximately 2 inches from ground level on the stand pipes. If plates are bolted to the stand pipe, the person installing the plate will be required to weld a pipe collar on the plate and place a minimum of two set screws/bolt on each collar. Aluminum data plates may be bolted with minimum ¼ inch bolt and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
 - a. First row: Operators name

e,

- b. Second row: Well name and number
- c. Third row: Legal location to include ¼ ¼, Section, Township, and range. If the legal location cannot be placed on one row it can be split into two rows with the ¼ ¼ (example: 1980 FNL 1980 FWL) being on the top row.
- d. Fourth row: Lease Number and API number.
 - i. Example marker plate: (attached)

NMOCD Order No. R-12965 also required the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a ground level dry hole marker was installed as required in the COA's from the BLM.

United States Department of the Interior



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Appropriate time for submittal would be when filing the Appropriate time for submittal would be when filing the Appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Solomon Hughes Natural Resource Specialist 575-234-5951

4

Jeffery Robertson Natural Resource Specialist 575-234-2230

Mike Burton Environmental Protection Specialist 575-234-2226

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Linda Denniston Environmental Protection Specialist 575-234-5974

Jesse Rice Natural Resource Specialist 575-234-5913 Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Amanda Lynch Natural Resource Specialist 575-234-5922

Duncan Whitlock Environmental Protection Specialist 575-234-5926

Tanner Nygren Natural Resource Specialist 575-234-5975

Indra Dahal Natural Resource Specialist 575-234-5996