

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company <b>COG Operating LLC</b>	Contact <b>Robert McNeill</b>
Address <b>600 W. Illinois Ave, Midland, Texas 79701</b>	Telephone No. <b>(432) 685-4332</b>
Facility Name <b>Lakewood AQE State SWD #1</b>	Facility Type <b>SWD</b>

Surface Owner: State	Mineral Owner	Lease No. (API#) 30-015-22233
----------------------	---------------	-------------------------------

**LOCATION OF RELEASE**

Unit Letter F	Section 30	Township 19S	Range 26E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.63342° N Longitude 104.42331° W

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release 500 bbls	Volume Recovered 480 bbls
Source of Release: Steel flow line	Date and Hour of Occurrence 7/22/2013	Date and Hour of Discovery 7/22/2013 6:15 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher - NMOCD</b>	
By Whom? Michelle Mullins	Date and Hour 7/22/2013 6:39 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A




Describe Cause of Problem and Remedial Action Taken.\*

A hole developed on the steel flow line due to corrosion. The line has been replaced to prevent reoccurrence.

Describe Area Affected and Cleanup Action Taken.\*

Initially 500bbls of produced water were released from a steel flow line, but using vacuum trucks, 480bbls were recovered. The spill was located north of the pad in the adjacent pasture. Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled to proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ike Tavarez (agent for COG)	Signed By:  Approved by District Supervisor:	
Title: Project Manager	Approval Date: 5/12/14	Expiration Date: NA
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval: 	Attached <input type="checkbox"/>
Date: 12-24-13	Phone: (432) 682-4559	

\* Attach Additional Sheets If Necessary

2RP-1748