

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
State of New Mexico
Energy Minerals and Natural Resources

JUL 23 2014

RECEIVED

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

AB1420537731

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production 6137	Contact Tracy Kidd
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.513.0628
Facility Name H B 10 Fed 1H	Facility Type Oil Well

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-29157
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	24S	29E	1650	North	990	East	Eddy

Latitude: 32.234873278

Longitude: -103.966670224

NATURE OF RELEASE

Type of Release Spill	Volume of Release 10BBLS	Volume Recovered 0BBLS
Source of Release Circulating pump line	Date and Hour of Occurrence July 20, 2014 11:00 AM	Date and Hour of Discovery July 20, 2014 11:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson; BLM & Thomas Oberding; OCD	
By Whom? Joah Weidemann	Date and Hour 7/21/2014 2:15 PM & 3:36 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A


Describe Cause of Problem and Remedial Action Taken.*

External corrosion on circulating pump line. Once the leak in the line was found it was de-energized and isolated. Line is in the process of being replaced and being wax taped to prevent corrosion in the future.

Describe Area Affected and Cleanup Action Taken.*

10 BBLS of oil leaked from the 2" steel circulating pump line where the line was buried under the firewall. The leak was due to external corrosion. The 10 BBLS were contained within the earthen containment. 0 BBLS were recovered. Size of the area affected: 60'x2'.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sandra Farley	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 7/24/2014	Expiration Date: N/A
E-mail Address: Sandy.Farley@dmv.com	Conditions of Approval: remediation per OCU rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: July 22, 2014	Phone: 575.746.5587	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

8/24/14

RP2-2390