Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-21141 5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.	STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District <u>IV</u> – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Holstun SWD
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SWD	8. Well Number
	1
2. Name of Operator	9. OGRID Number
Nearburg Producing Corporation	015742
3. Address of Operator 3300 N A St., Bldg 2, Ste 120, Midland, TX 79705	10. Pool name or Wildcat SWD Devonian
4. Well Location	
Unit Letter B: 660 feet from the North line and 1980 feet fr	
Section 4 Township 20S Range 25E NMPM Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3592.6 GR	
12. Charle Annuaniste Deute Indiante Nation (DI die	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] REMEDIAL WOR	
TEMPORARILY ABANDON 🗍 CHANGE PLANS 🗍 COMMENCE DRI	—
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🗌 CASING/CEMEN	Г ЈОВ
OTHER: OTHER: Repair	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.	npletions: Attach wellbore diagram of
proposed completion of recompletion.	
Worked over well 3/17-26/2015. Pulled tubing and packer to replace bad tubing (1 joint wi	th hole, 11 bad joints total). Set RBP and
Worked over well 3/17-26/2015. Pulled tubing and packer to replace bad tubing (1 joint wittested up the hole to determine casing integrity. Determined previous problem was faulty p	acker seal. Casing tested good. Ran internally
	acker seal. Casing tested good. Ran internally
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure.
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to $500\#$ for NMOCD witnessed MIT on $3/27/2015$ and okayed return to injection	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure.
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to $500\#$ for NMOCD witnessed MIT on $3/27/2015$ and okayed return to injection	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to $500\#$ for NMOCD witnessed MIT on $3/27/2015$ and okayed return to injection	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to $500\#$ for NMOCD witnessed MIT on $3/27/2015$ and okayed return to injection	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure.
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to $500\#$ for NMOCD witnessed MIT on $3/27/2015$ and okayed return to injection	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to $500\#$ for NMOCD witnessed MIT on $3/27/2015$ and okayed return to injection	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection. Resultion of Prever? See attached br	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to $500\#$ for NMOCD witnessed MIT on $3/27/2015$ and okayed return to injection	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection. Resurtor of Prever? See attached br	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection.	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015 RECEIVED
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection. Resultion of Prever? See attached br	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015 RECEIVED
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection.	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015 RECEIVED e and belief.
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection.	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015 RECEIVED e and belief.
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection.	e and belief.
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection.	e and belief.
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection.	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015 RECEIVED e and belief. 3-3/-/5 432-818-2940
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection.	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015 RECEIVED e and belief. 3-3/-/5 432-818-2940
tested up the hole to determine casing integrity. Determined previous problem was faulty p coated tubing and refurbished packer back in hole. Set packer and tested casing to 500# for NMOCD witnessed MIT on 3/27/2015 and okayed return to injection.	acker seal. Casing tested good. Ran internally 30 minutes w/ no loss of pressure. NM OIL CONSERVATION ARTESIA DISTRICT APR 0 6 2015 RECEIVED e and belief. 3-3/-/5 432-818-2940

Nearburg Producing Company

Rod and Tubing Detail as of : 3-25-2015 Bill Young

.

1

Well Name Holstun SWD #1

Tubing Detail:

.

1	2 3/8" x 5 1/2" AS 1x pkr (nickel plated) w/ pump out plug WLE	5.85	
Í	2 3/8" Pump Out Plug WEG	0.35	
	Equipment below seating nipple	6.20	
1	2 3/8" x 4 1/2" AS T2 On/Off tool w/ 1.875" Baker F sst profile	1.71	
1	2 7/8" 8rd (box) x 2 3/8" 8rd (pin) SST x-over	0.28	
322	2 7/8" L-80 6.5# EUE 8rd IPC (TK70) tubing	10163.12	
	Equipment above seating nipple	10165.11	
	Distance RKB to tbg hanger	16.00	
	Less length of compression	10181.11 4.38	
	Effective setting depth of seating nipple	10176.73	
	Bottom of WLEG	10182.93	Packer Depth
	Perfs @ 10,274'- 10,600' (open hole) PBTD @ 10,600'.		ŕ
	Pkr set @ 10,182.93' Bill Young		