Form 3160-5 (August 2007) NM OB GONSERVATION

ARTESIA OF THE SIA

PR APR 13 2015

**UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

	ONIDIN	U. 1	JU4-	CCIO
	Expires:	July	31,	2010
ease Seri	al No			

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter & E	CETVED
Do not use this form for proposals to drill or to re-enter and	سلم المال

NMNM0560353

abandoned we	6. If Indian, Allo	6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.  1. Type of Well				7. If Unit or CA/Agreement, Name and/or No. NMNM126412X  8. Well Name and No. BENSON DELAWARE FEDERAL UNIT 24		
						Oil Well Gas Well Otl  2. Name of Operator
CHI OPERATING INC	Contact: PAM E-Mail: pamc@chienerg					
3a. Address P.O. BOX 1799 MIDLAND, TX 79702	Phone No. (include area code 432-685-5001 432-687-2662	10. Field and Po BENSON E	10. Field and Pool, or Exploratory BENSON DELAWARE			
4. Location of Well (Footage, Sec., T	11. County or Pa	11. County or Parish, and State				
Sec 11 T19S R30E Mer NMP	EDDY COL	EDDY COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO INI	DICATE NATURE OF	NOTICE, REPORT, OR O	THER DATA		
TYPE OF SUBMISSION		ТҮРЕ О	F ACTION			
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resum	e) Water Shut-Off		
	☐ Alter Casing	☐ Fracture Treat	□ Reclamation	Well Integrity		
Subsequent Report	☐ Casing Repair	■ New Construction	□ Recomplete	☑ Other		
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	□ Temporarily Abandon			
	Convert to Injection	☐ Plug Back	☐ Water Disposal			
CHI Operating, Inc Benson SL: 1040' FNL & 125' FE Prod Zone: 1650' FNL & 330'  Approved APD will expire at tl CHI Operating, Inc. is request	EL FEL he end of August 2014. ing an extension.		APPROVED FOR 12 ENDING 8-24-	MONTH PERIOD		
	CTENDED APPROVI	AL FOR ON	E YEAR JER	9/12/14		
14. I hereby certify that the foregoing is	For CHI OPERA For CHI OPERA Committed to AFMSS for pro	TING INC, sent to the Ca cessing by JERRY BLAK	arlsbad LEY on 09/10/2014 ()			
Name(Printed/Typed) CLIF MA	NN	Title FIELD	SUPERVISOR			
Signature (Electronic S	Submission)	Date 08/08/2	2014			
	THIS SPACE FOR F	EDERAL OR STATE	OFFICE USE			
Approved By	- Mas Entagon	Title FIE	LD MANAGER	Date 4/7/ 18		
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condition	uitable title to those rights in the subje	arrant or ct lease Office CARLSB	Office CARLSBAD FIELD OFFICE			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime statements or representations as to any	for any person knowingly and matter within its jurisdiction	d willfully to make to any departme	ent or agency of the United		

# APD EXTENSION CONDITIONS OF APPROVAL

OPERATOR'S NAME:

Chi Operating

LEASE NO.:

NMNM 0560353

WELL NAME & NO.:

Benson Delaware Unit 24 1040' FNL & 125' FEL

SURFACE HOLE FOOTAGE: BOTTOM HOLE FOOTAGE

1650" FNL & 330 FEL

LOCATION:

Section 11, T. 19 S., R 30 E., NMPM

COUNTY:

Eddy County, New Mexico

The Pecos District Conditions of Approval (COA) that were approved with the APD on 08/24//2012 for Unit 23 and 09/19/2012 apply to this APD extension. The following conditions apply to the APD extension as well.

## I. DRILLING

# A. DRILLING OPERATIONS REQUIREMENTS

The BLM is to be notified a minimum of 4 hours in advance for a representative to witness:

- a. Spudding well
- b. Setting and/or Cementing of all casing strings
- c. BOPE tests

# **Eddy County**

Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822

- 1. Due to recent H2S encounters in the salt formation, it is recommended that monitoring equipment be onsite for potential Hydrogen Sulfide prior to drilling out the surface shoe. If Hydrogen Sulfide is encountered, please report measurements and formations to the BLM.
- 2. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without

prior approval. If the drilling rig is removed without approval – an Incident of Non-Compliance will be written and will be a "Major" violation.

3. The record of the drilling rate along with the GR/N well log run from TD to surface shall be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

#### B. CASING

Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.).

Centralizers required on surface casing per Onshore Order 2.III.B.1.f.

#### Wait on cement (WOC) for Potash Areas:

After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi for all cement blends, 2) until cement has been in place at least 24 hours. WOC time will be recorded in the driller's log.

No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.

#### Secretary's Potash

Possible brine/water flows in the Salado and Artesia groups. Possible lost circulation in the Artesia group.

- 1. The 13-3/8 inch surface casing shall be set at approximately 460 feet (a minimum of 25 feet into the Rustler Anhydrite and above the salt) and cemented to the surface. Additional cement may be required. Excess calculates to only 46%.
  - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.

- b. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry.
- c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- d. If cement falls back, remedial cementing will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the 8-5/8 inch intermediate casing is:

Option 1 Single Stage:

Cement to surface. If cement does not circulate see B.1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to potash. Additional cement may be required. Excess

Option #2 Two Stage:

- a. First stage to DV tool:
- □ Cement to circulate. If cement does not circulate, contact the appropriate
   □ BLM-office-before-proceeding-with-second-stage-cement-job. Operator-should have plans as to how they will achieve circulation on the next stage.
- b. Second stage above DV tool:

cement calculates to negative 21%.

- □ Cement to surface. If cement does not circulate see B.1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to potash.
- 3. The minimum required fill of cement behind the **5-1/2** inch production casing is:
  - □ Cement to surface. If cement does not circulate, contact the appropriate BLM office. Additional cement may be required as the excess cement calculates to 14%.
- 4. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

#### C. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **2000** (**2M**) psi.
  - a. **For surface casing only:** If the BOP/BOPE is to be tested against casing, the wait on cement (WOC) time for that casing is to be met (see WOC statement at start of casing section). Independent service company required.
- 3. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
  - a. In potash areas, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. For all casing strings, casing cut-off and BOP installation can be initiated at twelve hours after bumping the plug. However, **no tests** shall commence until the cement has had a minimum of 24 hours setup time.
  - b. The tests shall be done by an independent service company utilizing a test plug **not a cup or J-packer**. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (18 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).
  - c. The results of the test shall be reported to the appropriate BLM office.
  - d. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
  - e. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.

#### D. DRILL STEM TEST

If drill stem tests are performed, Onshore Order 2.III.D shall be followed.

## E. WASTE MATERIAL AND FLUIDS

All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area.

Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

CRW 04/14/15