Submit 1 Copy To Appropriate District Office	State of New Mex	ico.	Form C-103
Office District I – (575) 393-616 1625 N. French Dr., Hobbit Mr. 82240  DISTRICTOR OF TESTA DISTR	<b>yAŢļOM</b> inerals and Natura	l Resources	Revised August 1, 2011
1625 N. French Dr., Hobby MM 88240 District II – (575) 748-1283 ARTESIA DISTR	ICT	WELL A	
District II – (575) 748-1283 ARTESIA 518 811 S. First St., Artesia, NM 88210 1118 1 0 2	HL CONSERVATION I	DIVISION 30-015-2	
District III - (505) 334-6178 JUN 1.0 2010 1220 South St. Francis Dr.		is Dr 5. Indica	te Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 875	31	ATE X FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM <b>RECEIVE</b>	D Santa Te, Trivi 075	6. State (	Oil & Gas Lease No.
87505			
	ND REPORTS ON WELLS		Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO		CLICII	
DIFFERENT RESERVOIR. USE "APPLICATION I PROPOSALS.)	FOR PERMIT" (FORM C-101) FOR	L12317	ATE UNIT
1. Type of Well: Oil Well X Gas Wel	ll Other	8. Well 1	Number
		119	
2. Name of Operator		l l	D Number
COG OPERATING LLC		229137	*****
3. Address of Operator	V A C 70701		name or Wildcat
600 W. ILLINOIS AVE., MIDLAND, TEX	XAS /9/01	GRAYBU	JRG-JACKSON
4. Well Location			
Unit Letter; K; 1625 fe	et from the SOUTH line	e and 2630 feet from the	e WEST line
Section 16	Township 17S	Range 30E	NMPM EDDY County
nestra Amerika Mase a Amerika 1881 - 11. E	levation (Show whether DR, R		and the second second
	3,672' - GI	· · · · · · · · · · · · · · · · · · ·	
			Tomore a force with the second
12 Check Approp	riate Box to Indicate Nat	ure of Notice Report or	Other Data
12. Check Approp	rate Box to indicate ivat	are or routee, report or	Other Data
NOTICE OF INTENT	ION TO:	SUBSEQUEN	NT REPORT OF:
	·	REMEDIAL WORK	☐ ALTERING CASING ☐
		COMMENCE DRILLING OPN	<del></del>
- <del></del>		CASING/CEMENT JOB	П
PULL OR ALTER CASING MULT		CASING/CEMENT JOB	□
- <del></del>		CASING/CEMENT JOB	□ TQ 2863
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE OTHER:		OTHER: WELL PLUGGED	一 介
PULL OR ALTER CASING   MULT DOWNHOLE COMMINGLE		OTHER: WELL PLUGGED	一 介
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE  OTHER:  13. Describe proposed or completed op of starting any proposed work). SE	erations. (Clearly state all per EE RULE 19.15.7.14 NMAC.	OTHER: WELL PLUGGED tinent details, and give perti	AND ABANDONED 05/27/15.  nent dates, including estimated date
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE  OTHER:  13. Describe proposed or completed op	erations. (Clearly state all per EE RULE 19.15.7.14 NMAC.	OTHER: WELL PLUGGED tinent details, and give perti	AND ABANDONED 05/27/15.  nent dates, including estimated date
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE  OTHER:  13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletic	TIPLE COMPL (Control of the control	OTHER: WELL PLUGGED rtinent details, and give pertinent Multiple Completions:	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of
PULL OR ALTER CASING  MULT DOWNHOLE COMMINGLE  MULT OTHER:  13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion of 5/22/15: SET 4-1/2" CIBP @ 2,499"; PUM	TIPLE COMPL  Greations. (Clearly state all per EE RULE 19.15.7.14 NMAC. on.  SP 60 SXS. CMT. W/ 2%CAC	OTHER: WELL PLUGGED rtinent details, and give pertinent Multiple Completions:  EL @ 2,499'; WOC X TAG O	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE  OTHER:  13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion.  05/22/15: SET 4-1/2" CIBP @ 2,499"; PUM CIRC. WELL W/ PXA FLUID; P	riple compl	OTHER: WELL PLUGGED rtinent details, and give pertinent Multiple Completions:  L @ 2,499'; WOC X TAG (@ 1,065'; WOC.	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);
PULL OR ALTER CASING	rerations. (Clearly state all percent on.  ER RULE 19.15.7.14 NMAC. on.  EP 60 SXS. CMT. W/ 2%CAC ERF. X SQZ. 45 SXS. CMT. Z. 110 SXS. CMT. @ 590'; W	OTHER: WELL PLUGGED rtinent details, and give perticular for Multiple Completions:  EL @ 2,499'; WOC X TAG (@ 1,065'; WOC. WOC X TAG CMT. @ 485';	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);
PULL OR ALTER CASING  MULT DOWNHOLE COMMINGLE  MULT OTHER:  13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion of the completion of th	riple compl	DTHER: WELL PLUGGED rtinent details, and give perticular for Multiple Completions:  EL @ 2,499'; WOC X TAG (@ 1,065'; WOC. VOC X TAG CMT. @ 485'; D BY OCD).	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%
PULL OR ALTER CASING  MULT DOWNHOLE COMMINGLE  MULT OTHER:  13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion of starting any proposed work of starting any proposed or completed op of starting any proposed work of starting any proposed or completed op of starting any proposed work of starting any proposed work of starting any proposed or completed op of starting any proposed work of starting and starting a	riple compl	DTHER: WELL PLUGGED rtinent details, and give pertiance of Multiple Completions:  L @ 2,499'; WOC X TAG (@ 1,065'; WOC. WOC X TAG CMT. @ 485'; D BY OCD).  CMT. @ 63'-4'; DIG OUT	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3'
PULL OR ALTER CASING  MULT DOWNHOLE COMMINGLE  MULT OTHER:  13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion of the completion of th	riple compl	DTHER: WELL PLUGGED rtinent details, and give pertiance of Multiple Completions:  L @ 2,499'; WOC X TAG (@ 1,065'; WOC. WOC X TAG CMT. @ 485'; D BY OCD).  CMT. @ 63'-4'; DIG OUT	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3'
PULL OR ALTER CASING  MULT DOWNHOLE COMMINGLE  MULT OTHER:  13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion of starting any proposed work of starting any proposed or completed op of starting any proposed work of starting any proposed or completed op of starting any proposed work of starting any proposed work of starting any proposed or completed op of starting any proposed work of starting and starting a	riple compl	DTHER: WELL PLUGGED rtinent details, and give pertiance of Multiple Completions:  L @ 2,499'; WOC X TAG (@ 1,065'; WOC. WOC X TAG CMT. @ 485'; D BY OCD).  CMT. @ 63'-4'; DIG OUT	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3'
PULL OR ALTER CASING  MULT DOWNHOLE COMMINGLE  MULT OTHER:  13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion of starting any proposed work of starting any proposed or completed op of starting any proposed work of starting any proposed or completed op of starting any proposed work of starting any proposed work of starting any proposed or completed op of starting any proposed work of starting and starting a	riple compl	DTHER: WELL PLUGGED rtinent details, and give pertiance of Multiple Completions:  L @ 2,499'; WOC X TAG (@ 1,065'; WOC. WOC X TAG CMT. @ 485'; D BY OCD).  CMT. @ 63'-4'; DIG OUT	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3'
PULL OR ALTER CASING	rerations. (Clearly state all persections.)  ER RULE 19.15.7.14 NMAC.  On.  EP 60 SXS. CMT. W/ 2%CAC ERF. X SQZ. 45 SXS. CMT. Z. 110 SXS. CMT. @ 590'; V ZX TAG CMT. @ 10' (OK' ING ALL ANNULI, 45 SXS. E. ON ALL ANNULI; WELD	DTHER: WELL PLUGGED rtinent details, and give pertiinent details, and give	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3'
PULL OR ALTER CASING  MULT DOWNHOLE COMMINGLE  MULT OTHER:  13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion of starting any proposed work of starting any proposed or completed op of starting any proposed work of starting any proposed or completed op of starting any proposed or completed op of starting any proposed work). SE proposed completed op of starting any proposed or completed op of starting any proposed work). SE proposed completed op of starting any proposed work of starting and starting any proposed work of starting any proposed work of starting and starting any proposed work of starting and starting	riple compl	DTHER: WELL PLUGGED rtinent details, and give pertiinent details, and give	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3'
PULL OR ALTER CASING	rerations. (Clearly state all persections.)  ER RULE 19.15.7.14 NMAC.  On.  EP 60 SXS. CMT. W/ 2%CAC ERF. X SQZ. 45 SXS. CMT. Z. 110 SXS. CMT. @ 590'; V ZX TAG CMT. @ 10' (OK' ING ALL ANNULI, 45 SXS. E. ON ALL ANNULI; WELD	DTHER: WELL PLUGGED rtinent details, and give pertiinent details, and give	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3'
PULL OR ALTER CASING	riple compl	DTHER: WELL PLUGGED rtinent details, and give pertiinent details, and give pertiinent Multiple Completions:  EL @ 2,499'; WOC X TAG O @ 1,065'; WOC. WOC X TAG CMT. @ 485'; D BY OCD). CMT. @ 63'-4'; DIG OUT ON STEEL PLATE X INST	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3' CALL DRY HOLE MARKER.
PULL OR ALTER CASING	riple compl	DTHER: WELL PLUGGED rtinent details, and give pertiinent details, and give pertiinent Multiple Completions:  EL @ 2,499'; WOC X TAG O @ 1,065'; WOC. WOC X TAG CMT. @ 485'; D BY OCD). CMT. @ 63'-4'; DIG OUT ON STEEL PLATE X INST	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3' CALL DRY HOLE MARKER.
PULL OR ALTER CASING	riple compl	DTHER: WELL PLUGGED rtinent details, and give pertiinent details, and give pertiinent Multiple Completions:  EL @ 2,499'; WOC X TAG O @ 1,065'; WOC. WOC X TAG CMT. @ 485'; D BY OCD). CMT. @ 63'-4'; DIG OUT ON STEEL PLATE X INST	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3' CALL DRY HOLE MARKER.
PULL OR ALTER CASING	rerations. (Clearly state all persections.)  ER RULE 19.15.7.14 NMAC.  On.  EP 60 SXS. CMT. W/ 2%CACERF. X SQZ. 45 SXS. CMT. Z. 110 SXS. CMT. @ 590'; VEX. TAG CMT. @ 110' (OK') ING ALL ANNULI, 45 SXS. E. ON ALL ANNULI; WELD  Rig Release Date  Strue and complete to the best	OTHER: WELL PLUGGED rtinent details, and give pertitions: For Multiple Completions:  EL @ 2,499'; WOC X TAG O @ 1,065'; WOC. WOC X TAG CMT. @ 485'; D BY OCD). CMT. @ 63'-4'; DIG OUT ON STEEL PLATE X INST	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3' TALL DRY HOLE MARKER.
PULL OR ALTER CASING	riple compl	OTHER: WELL PLUGGED rtinent details, and give pertitions: For Multiple Completions:  EL @ 2,499'; WOC X TAG O @ 1,065'; WOC. WOC X TAG CMT. @ 485'; D BY OCD). CMT. @ 63'-4'; DIG OUT ON STEEL PLATE X INST	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3' CALL DRY HOLE MARKER.
PULL OR ALTER CASING	rerations. (Clearly state all persections.)  BY 60 SXS. CMT. W/ 2%CACCERF. X SQZ. 45 SXS. CMT. Z. 110 SXS. CMT. @ 590'; WO X TAG CMT. @ 110' (OK') ING ALL ANNULI, 45 SXS. E. ON ALL ANNULI; WELD  Rig Release Date  Strue and complete to the best  TITLE: AGEN'	DTHER: WELL PLUGGED rtinent details, and give pertiinent details, and give pertiinent for Multiple Completions:  L @ 2,499'; WOC X TAG C@ 1,065'; WOC. WOC X TAG CMT. @ 485'; DBY OCD). CMT. @ 63'-4'; DIG OUT ON STEEL PLATE X INST	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3' TALL DRY HOLE MARKER.
PULL OR ALTER CASING	rerations. (Clearly state all persections.)  BY 60 SXS. CMT. W/ 2%CACCERF. X SQZ. 45 SXS. CMT. Z. 110 SXS. CMT. @ 590'; WO X TAG CMT. @ 110' (OK') ING ALL ANNULI, 45 SXS. E. ON ALL ANNULI; WELD  Rig Release Date  Strue and complete to the best  TITLE: AGEN'	OTHER: WELL PLUGGED rtinent details, and give pertitions: For Multiple Completions:  EL @ 2,499'; WOC X TAG O @ 1,065'; WOC. WOC X TAG CMT. @ 485'; D BY OCD). CMT. @ 63'-4'; DIG OUT ON STEEL PLATE X INST	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3' TALL DRY HOLE MARKER.
PULL OR ALTER CASING	rerations. (Clearly state all persections.)  BY 60 SXS. CMT. W/ 2%CACCERF. X SQZ. 45 SXS. CMT. Z. 110 SXS. CMT. @ 590'; WO X TAG CMT. @ 110' (OK') ING ALL ANNULI, 45 SXS. E. ON ALL ANNULI; WELD  Rig Release Date  Strue and complete to the best  TITLE: AGEN'	DTHER: WELL PLUGGED rtinent details, and give pertiinent details, and give pertiinent for Multiple Completions:  L @ 2,499'; WOC X TAG C@ 1,065'; WOC. WOC X TAG CMT. @ 485'; DBY OCD). CMT. @ 63'-4'; DIG OUT ON STEEL PLATE X INST	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3' TALL DRY HOLE MARKER.
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER:  13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion of starting any proposed work). SE proposed completion or recompletion of starting any proposed work). SE proposed completion or recompletion of starting any proposed work). SE proposed completion or recompletion of starting any proposed work). SE proposed completion or recompletion of starting any proposed work). SE proposed completion or recompletion of starting any proposed work). SE proposed completion or recompletion of starting any proposed work). SE proposed completion or recompletion of starting any proposed work). SE proposed completion or recompletion or recomp	rerations. (Clearly state all persections.)  BY 60 SXS. CMT. W/ 2%CACCERF. X SQZ. 45 SXS. CMT. Z. 110 SXS. CMT. @ 590'; WO X TAG CMT. @ 110' (OK') ING ALL ANNULI, 45 SXS. E. ON ALL ANNULI; WELD  Rig Release Date  Strue and complete to the best  TITLE: AGEN'	DTHER: WELL PLUGGED rtinent details, and give pertiinent details, and give pertiinent for Multiple Completions:  L @ 2,499'; WOC X TAG C@ 1,065'; WOC. WOC X TAG CMT. @ 485'; DBY OCD). CMT. @ 63'-4'; DIG OUT ON STEEL PLATE X INST	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of  CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3'  ALL DRY HOLE MARKER.
PULL OR ALTER CASING	erations. (Clearly state all per EE RULE 19.15.7.14 NMAC. on.  PP 60 SXS. CMT. W/ 2%CAC ERF. X SQZ. 45 SXS. CMT. Z. 110 SXS. CMT. @ 590'; W X TAG CMT. @ 110' (OK' ING ALL ANNULI, 45 SXS. F. ON ALL ANNULI; WELD  Rig Release Date  Strue and complete to the best Strue and Complete a	DTHER: WELL PLUGGED rtinent details, and give pertiinent details, and give pertiinent for Multiple Completions:  L @ 2,499'; WOC X TAG C@ 1,065'; WOC. WOC X TAG CMT. @ 485'; DBY OCD). CMT. @ 63'-4'; DIG OUT ON STEEL PLATE X INST	AND ABANDONED 05/27/15.  nent dates, including estimated date Attach wellbore diagram of CMT. @ 1,940' (OK'D BY OCD);  PUMP 25 SXS. CMT. W/ 2%  X CUT OFF WELLHEAD 3' TALL DRY HOLE MARKER.

★ Submit C-103 Subsequent

Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.