

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action



NAB1518136975		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company RKI E&P, LLC		Contact Taylor Jones			
Address 210 Park Ave. - Ste. 700, OKC, OK 73102		Telephone No. 405-996-5782			
Facility Name: North Brushy Draw 35-9H		Facility Type : Oil and Gas Well			
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-42220	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	25S	29E	300	FNL	260	FEL	Eddy

Latitude: 32.0926101 Longitude: -103.9468205

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 70 Bbls	Volume Recovered: 60 Bbls
Source of Release Suction screen pot on Jet pump	Date and Hour of Occurrence 06/23/15 - 1015hrs MT	Date and Hour of Discovery 06/23/15 - 1015hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson	
By Whom? Taylor Jones	Date and Hour: 06/24/15 - 1330hrs CT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A bolt broke on the suction screen pot of the jet pump. Isolated the leak and replaced the bolt.		
Describe Area Affected and Cleanup Action Taken.* Fluid was standing around the Jet pump skid and around production tanks. Some fluid did run off of location. Vacuum truck was dispatched to recover free standing fluid, approximately 60 Bbls recovered. Offsite affected soil will be dug and hauled.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Taylor Jones	Approved by Environmental Specialist: 	
Title: EHS Systems Specialist	Approval Date: 6/30/15	Expiration Date: N/A
E-mail Address: Tjones@rkixp.com	Conditions of Approval:	
Date: 06/24/15 Phone: 405-996-5782	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/11/15

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 24 2015

RECEIVED

2 RP-3080