

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

MAR 03 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd. <i>11010910</i>	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Harroun 15-3 SWD Facility	Facility Type	SWD
Surface Owner	Fee	Mineral Owner	API No. 30-015-29233

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	15	24S	29E					Eddy County, NM

Latitude N 32.21990° Longitude W 103.96496°

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	40 bbls	Volume Recovered	38 bbls
Source of Release	Stress/fatigue of a 4 inch steel suction line from tank to pump	Date and Hour of Occurrence	02/16/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	02/17/2016 @ 8:25 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Stress/fatigue of a 4 inch steel suction line caused 40 bbls of produced water to spill into the lined containment. Approximately 38 bbls of produced water were recovered and the line was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 45' x 45' with all of the leak staying inside the lined battery on location. Remediation will be completed by removing the contaminated materials from within the lined containment and replacing them with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Casey Summers	Approved by Environmental Specialist:	
Title:	NM Environmental Advisor	Approval Date:	3/3/15
E-mail Address:	casey_summers@oxy.com	Expiration Date:	N/A
Date:	3-2-16	Phone:	(575) 513-8289

Conditions of Approval:  
Remediation per O.C.D. Rules & Guidelines checked   
**SUBMIT REMEDIATION PROPOSAL NO**

LATER THAN: 4/4/16

\* Attach Additional Sheets If Necessary

2 RP. 35A1