NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division

1220 S. St. Francis Dr., Santa Fe, NM 87505

JUN 07 2016

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in **RECEIVED** rdance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1414 054 900						OPERA:	ГOR		✓ Initia	al Report		Final Report	
Name of Company Devon Energy Production Company 4/37													
Address 64				NM 88210		Telephone No. 575.513.5767							
Facility Name Aldabra 25 Federal 7H Facility Type Oil													
Surface Owner Federal Mineral Owner							Federal API No 30-015-38602						
LOCATION OF RELEASE													
						1			West Line County				
P	25	23S	31E	200		FSL	1050]	FEL	Eddy			
Latitude: 32.1607 Longitude: 103.4335													
NATURE OF RELEASE													
Type of Release Oil							Volume of Release Volume Recover 25BBLS 15BBLS						
Source of Release							Date and Hour of Occurrence Date and Hou					v	
Horizontal Separator							6/6/16 @7:00AM 6/6/16 @7:00AM						
Was Immediate Notice Given?							If YES, To Whom?						
☐ Yes ☐ No ☐ Not Required						I OCD-Mike Bratcher BLM-Shelly Tucker							
By Whom?						Date and Hour							
Jeremy Porras, Assistant Production Foreman						OCD-6/6/2016 @8:16AM							
W 3V-4 D110						BLM-6/6/2016 @8:14AM If YES, Volume Impacting the Watercourse							
Was a Watercourse Reached? ☐ Yes ☑ No						N/A							
If a Watercourse was Impacted, Describe Fully.* N/A													
Describe Cause of Problem and Remedial Action Taken.*													
25BBLS of oil was released. The release originated on the manway gasket on the horizontal separator due to wear and tear. The valve was shut off to prevent further release and isolate the leak. A new gasket was installed.													
prevent tuttin	er reiense a	nd isolate inc	icak. A iii	ew gasket was ins	anca.								
Describe Are								-					
				l separator. The re									
side of pad. 15BBLS of oil was recovered via vacuum truck. The approximate size of the total affected area including vegetation spray was 100ft by 100ft on the Northeast of location. An environmental company will be contacted for remediation.													
I harshy cartify that the information given shows is true and complete to the heat of my knowledge and understand that pursuant to NMOCD rules and													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature: Dana DeLaRosa						OIL CONSERVATION DIVISION							
							Dinan Alla						
							Approved by Environmental Specialist.						
Title: Field Admin Support							Approval Date: U8 116 Expiration Date: N/A						
E-mail Addre	ess: dana.de	larosa @dvn.	.com			Conditions of Approval. C.D. Rules & Guide ines Attached							
Date: 616	/2016	SUBMIT REMEDIATION PROPOSAL NO											
	Attach Additional Sheets If Necessary SUBMIT REMEDIATION AREA 3124												
			-							UIL	, –	141 .	