Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103		
District 1 – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013		
1625 N. French Dr., Hohbs, NM 88240		WELL API NO.		
District II - (575) 748-1283	OIL CONSERVATION DIVISION	30-015-42754		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE		
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM		VO-5866		
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7 Longo Morris on Linit A sussessed blows		
1	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Humidor BMO State Com		
DIFFERENT RESERVOIR. USE "APPL"	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Humdor Bivio State Com		
PROPOSALS.)	Gas Well Other Oth	N 8. Well Number		
1. Type of Well: Oil Well 🛛	Gas Well Other ARTESIA DISTRICT			
2. Name of Operator		9. OGRID Number		
Yates Petroleum Corporation	JUN 21 2016	025575		
3. Address of Operator		 Pool name or Wildcat Willow Lake; Bone Spring, West 		
105 South Fourth Street, Artesia,	105 South Fourth Street, Artesia, NM 88210			
4. Well Location				
Unit Letter E :	2625 feet from the North line and	400 feet from the West line		
Unit Letter D	230 feet from the North line and	660 feet from the West line		
Section 23	Township <u>24S</u> Range <u>27E</u>	NMPM <u>Eddy</u> County		
Section 14	Township 243 Range 272 Township $24S$ Range $27E$	NMPM <u>Eddy</u> County NMPM <u>Eddy</u> County		
	11. Elevation (Show whether DR, RKB, RT, GR,			
	3,219' GR			
	5,277 OK	NEARSTREE MARKEN AND AND AND AND AND AND AND AND AND AN		
12. Check	Appropriate Box to Indicate Nature of Not	ice, Report or Other Data		
	NTENTION TO: S	UBSEQUENT REPORT OF:		
		-		
PULL OR ALTER CASING				
CLOSED-LOOP SYSTEM		1		
OTHER:	pleted operations. (Clearly state all pertinent detail	a and give nortinent dates including estimates		
	vork). SEE RULE 19.15.7.14 NMAC. For Multiple			
proposed completion or re		e completions. Attach wendore diagram of		
proposed completion of re	completion.	`		

2

The well is free of water and we will use ready-mix dumping to plug the well. It has 10' of 30" culvert, cemented in place. From 10' to 125' is 20" hole and from 125'-155' is 9" hole: True hole volume is 56 bbl/314 ft/3 and 11.6 yd/3. Because of the time factor there will be some excess required after 1st dump, stringline can be ran into well to determine extra if needed, after filling we will remove locking device and install ground level dry hole marker and any needed cleanup will follow.

READY	Mix	HAS	to BE	THIN	ENOUGH	to	GAURANTEE	tihat	CEMENT	atts
TO THE	Batt	on of	s the d	RORE	LE				En all bore only.	

,	· · · · · · · · · · · · · · · · · · ·		Approved for plugging of Liability under bond is ret of C-103 (Subsequent Rep which may be found at Q	tained pending receipt port of Well Plugging) CD Web Page under
Spud Date:	10/28/14	Rig Release Date:	Forms, www.cmnrd.state.	nm.us/oed.
WELL MI	IST BE PLU99ED	BY 612112017		
I hereby certify SIGNATURE (11-11-1	e and complete to the best of my kr	Ū.	May 31, 2016
Type or print na For State Use O APPROVED B	Only Dala D	_ E-mail address: <u>tinah@yatesp</u> TITLE COMPLIANCE O	EFIRER DATE	
Conditions of A	nnroval (if any):	ATTACHED COA		1

CONDITIONS FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases

- 1. Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 7. Produced water will not be used during any part of the plugging operation.
- 8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 10. Class 'C' cement will be used above 7500 feet.
- 11. Class 'H' cement will be used below 7500 feet.
- 12. A cement plug is required to be set 50' above and 50' below, all casing shoes, casing stubs, DV tools, attempted casing cut offs, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 13. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 14. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 15. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, **(WOC 4 hrs and tag)**.
- 16. No more than **3000' is allowed between cement plugs in cased hole and 2000' in open** hole.
- 17. Formations to be isolated with cement plugs are:
 - A) Fusselman

م مشرقة لأ

- B) Devonian
- C) Morrow

- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo

مر_د ،

- I) Glorieta
- J) Yates.
- K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 18. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, cement will be set 50' below to 50' above perforation inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and well number
- 3. API number
- 4. Unit letter
- 5. Quarter section (feet from North, South, East or West)
- 6.Section, Township and Range
- 7. Plugging date
- 8. County

(SPECIAL CASES)

AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude be GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)