	Submit 1 Copy To Appropriate District Office	State of New Me			Form C-103
,,	<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natu		ELL API NO.	Revised July 18, 2013
	District II - (575) 748-1283	OIL CONSERVATION	DIVISION	40-	-005 - G3348
	811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Fran	1.5	Indicate Type of L	
	1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87	7505	STATE State Oil & Gas Le	FEEease No.
	1220 S. St. Francis Dr., Santa Fe, NM 87505			25891	
	SUNDRY NOTI	CES AND REPORTS ON WELLS			it Agreement Name
	(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC			1111. (5)	(122 11 51 )
	PROPOSALS.)	Gas Well 🛛 Other	<u> </u>	Well Number	7 33 7tale
	Type of Well: Oil Well      Name of Operator	Gas well My Other		OGRID Number	Diameter
	<u>lleliuna</u>	torgy, INC			149441
	3. Address of Operator 200 N Mainfeld Su	ite 1100 Midland, Tx	79701	). Pool name or Wil	ope Abo
	4. Well Location Unit Letter	660 feet from the North	line and (olo)	feet from th	e West line
	Section 33	Township H South Ra	<del></del>	<del></del>	ounty Charls
		11. Elevation (Show whether DR, 3845)			
١	and the same of the same of the same	יטוסל	6R	1 - 5 - N	The state of the s
	12. Check A	Appropriate Box to Indicate N	ature of Notice, Rep	port or Other Dat	ra
	NOTICE OF IN			QUENT REPO	
	PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	PLUG AND ABANDON ☒ CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLIN		FERING CASING ☐ .ND A ☐
	PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JO		IND A 🖂
	DOWNHOLE COMMINGLE			<del></del>	
	CLOSED-LOOP SYSTEM  OTHER:	П	OTHER:		П
•	13. Describe proposed or compl	leted operations. (Clearly state all p	pertinent details, and give		
	of starting any proposed wo proposed completion or reco	ork). SEE RULE 19.15.7.14 NMAC	C. For Multiple Comple	etions: Attach wellb	ore diagram of
į.		Start on 1 19 3,450. WOC 4 Tag.			
U	( ). Obt 6 3'200 tidl 2 (	X337 Cim( 10 71 (10 ) Was Car		~ 1 NN	in 0 < 111
,IX	1 20 r cont for 3005'-2	9051		(ut off	wellhead, install
- -	pt 30st cont fr. 2,014 -	1914 WOE + 1746		dig hole m	white clear laution.
);	bl JOH CALL II. allow	Approved	for plugging of well bore onleader bond is retained pendin	y.	
1	perf of Squeeze @ 943'.	10C & 1AC of C-103 (	Subsequent Report of Well P	lugging)	
			y be found at OCD Web Page ww.cmnrd.state.nm.us/ocd.	under	_
1	Part of Squeeze from 60	1-gutul.		· · · · · · · · · · · · · · · · · · ·	NM OIL CONSERVATIO
					ARTESIA DISTRICI
;	Spud Date: 4-10-20	Rig Release Da	te: 4-72	-2001	AUG 1 1 2016
			2/17	201	DECEWED.
	WELL MUST BE P			d balief	RECEIVED
	increby certify that the information a	100 ve is the and complete to the be	st of my knowledge and	d benet.	
!	SIGNATURE 7	TITLE S	Ops Free	DATE_	8/10/16
	Type or print name  For State Use Only	E-mail address	: westa reimid .co	or∕∕ PHONE	472-663-466
	APPROVED BY: Sleelet 2	Isl TITLE COMP	LIANCE OFFIC	DATE	8/12/16_
	Conditions of Approval (if any):				
	JF SE	E ATTACHED COA-	5		

# -WellView<sup>\*</sup>

# **Downhole Well Profile**

Well Name: Willow Spring '33' 3

	Surface Legal Location Sec. 33 4S 25E	Field Name Pecos Slope	State New Mexico	Well Configuration Type Vertical
Original KB Elevation (ft) 3,858.00			PBTD (Ail) (mKB) main hole - 4,935.0	Total Depth All (TVD) (ftKB)

Туре					=	
Des	Make	Model	WP (psi)	Service	WP Top (psi)	Bore Min (in)
	·					

Vertical - main hole, 7/27/2016 1:17:12 PM							
	Vertical schematic (actual)						
wi-4311>-3>> <del>y</del> rassasaankaq <del>y</del> lbess	FD						
_							
***************************************							
កក់វាស់បំសំប៉ាវិការសារ	្ត្រី ត្រូវការបានក្រុមក្រុមក្រុមក្រុមក្រុមក្រុមក្រុមក្រុម						
.23							
	kir						
······································							
₩1 I I	TOE - 1800' - TAT 1964'						
"''' ⊘ ≯	100 100						
<u></u>	E - TMT 19641						
ie,	1M1						
<del>-                                      </del>							
<del></del>							
<del></del>	M <del>K</del>						
W							
<u> </u>							
~~~~\\\\							
	<b>***********************************</b>						
<b>X</b>							
<b>※</b>							
	bh -						
Š.							
Ñ							
N.	i N.						
(A	<b>3.4</b> (2)						
	The state of the s						
Ö							
·····	6						
8							
 S	K = 1						
W.							
1							
	The a proper transport and the state of the						

Casing Strings					-	
Csg Des	T	OD (in)	Wt/Len (lb/ft)	Grade	Top Thread	Set Depth (ftKB)
Conductor	- [	16	65.0	H-40		43.0
Surface		11 3/4	42.0	H-40	ST&C	943.0
Intermediate		8 5/8	24.0	K-55	ST&C	1964.0
Production	•	5 1/2	15.5	J-55	LT&C	3945,0
Slim hole	-	2 7/8	6.5	J-55	EUE	5057.0
Porforations					<u> </u>	

Perforations			
Date	i Top (ftKB)	Btm (ftKB)	Linked Zone
6/2/2001	3,612.0	3,622.0	
5/24/2001	3,714.0	3,724.0	
5/20/2001	3,758.0	3,770.0	
8/15/2004	4,858.0	4,868.0	•••
8/15/2004	4,912.0	4,920.0	

**Tubing Strings** Set Depth (ftKB) 4,913.0 Tubing Description Production Run Date 8/26/2004 String Length (ft) 4,903.00 Item Des Make Model QD (in) Wt (!b/ft) Grade Len (ft) Jts T&C Upset 2.90 J-55 4,901 Tubing 1.9 8 .90 Seating Nipple 귀 T&C Upset 1.9 2.90 J-55 1.10

Rod Strings										
Rod Description Run Date			String Length (ft)	Set Depth (ftKB)						
Item Des	Jts	Make	Model	QD (in)	Wt (lb/ft)	Grade	Len (ft)			

Calculated

Rod. TOC

a year

Page 1/1

Report Printed: 7/27/2016

# CONDITIONS FOR PLUGGING AND ABANDONMENT

#### District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 7. Produced water will not be used during any part of the plugging operation.
- 8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbis of water.
- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 10. Class 'C' cement will be used above 7500 feet.
- 11. Class 'H' cement will be used below 7500 feet.
- 12. A cement plug is required to be set 50' above and 50' below, all casing shoes, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 13. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 14. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 15. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 16. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

- 17. Formations to be isolated with cement plugs are:
  - A) Fusselman
  - B) Devonian
  - C) Morrow
  - D) Wolfcamp
  - E) Bone Springs
  - F) Delaware
  - G) Any salt sections
  - H) Abo
  - I) Glorieta
  - J) Yates.
  - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 18. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

#### DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and well number
- 3. API number
- 4. Unit letter
- 5. Quarter section (feet from North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging date
- 8. County

## (SPECIAL CASES)

## AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)