Submit 1 Copy To Appropriate District Office	State of New M			Form C-103
District'l – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.	
<u>District II</u> – (575) 748-1283	OIL CONSERVATION	NDIVISION	30-015-22053	
811 S. First St., Artesia, NM 88210 <u>District_III</u> – (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE	FEE 🛛
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa i C, i vivi C	,,,,,,,,	6. State Oil & Gas	Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7 Lease Name or I	Jnit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Pipkin HE Com	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well Gas Well Other			1	
2. Name of Operator			9. OGRID Number	
Yates Petroleum Corporation 3. Address of Operator			025575 10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210			Eagle Creek; Permo Penn	
4. Well Location			,	
Unit Letter M :	660 feet from the Sou	th line and	660 feet from the	ne <u>West</u> line
Section 4	Township 18S R	ange 25E	NMPM Eddy	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3559'GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN	NTENTION TO:	SUB	SEQUENT REP	ORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR				LTERING CASING
TEMPORARILY ABANDON	— — —			AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB ∐	
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM				
OTHER:		OTHER:		
	oleted operations. (Clearly state all			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
Yates Petroleum Corporation plans to plug and abandon this well as follows:				
1. MIRU all safety equipment as needed. NU BOP. No casing recovery will be attempted. TOH with production equipment.				
2. Pamp 25 bbls plugging mud, spot a 25 sx Class "H" cement plug from 8012"-8312". This will leave a plug across Morrow top: 3. Spot a 25 sx Class "H" cement plug from 7100". This will leave a plug across Canyon top.				
4. Set a CIBP at 6568' and cap it with 40 sx Class "C" cement. This will leave a plug over open Wolfcamp perfs and the TOC.—Wolf + 746.				
5. Perforate at 5287' and spot a 60 sx Class "C" cement plug from 5087'-5287', inside and outside the production casing across Wolfcamp. WOC and				
tag, reset if necessary. 6. Perforate at 4130' and spot a 60 sx Class "C" cement plug from 3930'-4130', inside and outside the production easing across Abo top. WOC and tag,				
reset if necessary.				
7. Perforate at 2173' and spot a 60 sx Class "C" cement plug from 1973'-2173', inside and outside the production casing across Glorieta top. WOC and tag, reset if necessary.				
8. Perforate at 1200' and spot a 60 sx Class "C" cement plug from 1000'-1200', inside and outside the production casing across casing shoe. WOC and				
tag, reset if necessary. 9. Perforate at 406' and establish circulation up the 4-1/2" x 8-5/8" annulus, then spot a 105 sx Class "C" cement plug from 0 to 406', inside and outside				
production casing. This will form the casing shoe plug and the surface plug. WOC and tag, reset if necessary.				
10. Remove all surface equipment and v	veld dry hole marker per regulations.			NM OIL CONSERVATION
Wellbore schematics attached		Approved for plugging of Liability under bond is a	of well bore only.	ARTESIA DISTRICT
0.10	2: 21 - 5	of C-103 (Subsequent R	eport of Well Plugging)	AUG 2 9 2016
Spud Date:	Rig Release L	atesh may be found at (Forms, www.cmprd.state		
WELL MUST BE P	LUBBED BY 8/30.			RECEIVED
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE (Line) Live Ta) TITLE Regulatory Reporting Supervisor DATE August 25, 2016				
The state of the s				
Type or print name Tina Huerta E-mail address: tinah@yatespetroleum.com PHONE: 575-748-4168				
For State Use Only				
APPROVED BY: Salut I ky TITLE COMPLIANCE OFFICER DATE 8/30/2016				
APPROVED BY: flatet 2 Rest TITLE Complianace of FICER DATE 8/30/2016 Conditions of Approval (if any): SEE ATTACHEO COA-5				
SEE HITHUHED COH-5				

WELL NAME: PIPKIN HE COM No. 01 FIELD: Eagle Creek Permo Penn LOCATION: 660 FSL & 660 FWL of Section 4-18S-25E Eddy Co., NM **GL**: 3,559' **ZERO**: 15' **KB**: 3,574' **CASING PROGRAM SPUD DATE**: 02/17/77 **COMPLETION DATE**: 04/05/77 COMMENTS: API No.: 30-015-22053 13-3/8" 64# H-40 356' NSL Order # 5377 -2-22-77 8-5/8" 24# J-55 1,150' Surface 17-1/2" Hole 4.5" 11.6# K-55 729' 4.5" 10.5# K-55 5,890' 8,518' 4.5" 11.6# K-55 1,899' **Bottom Hole** 13-3/8" @ 356' **Before** w\ 380 sx (Circ.) 12-1/4" Hole **TOPS** SA 695' Glorieta 2.123 8-5/8" @ 1,150" 4,080' Abo w\800 sx (Circ.) Wolfcamp 5,237' 7,350 Canyon 7,628' Strawn 7-7/8" Hole Atoka 8,141' Morrow 8,262' 8,508' Chester TOC @ 6,100' Wolfcamp Perfs: 6,618'-6,674' (120) 4-1/2"" @ 8,518' Not to Scale w\ 675 sx 07/20/16 FC: 8,485 JMH TD: 8,560'

WELL NAME: PIPKIN HE COM No. 01 FIELD: Eagle Creek Permo Penn LOCATION: 660 FSL & 660 FWL of Section 4-18S-25E Eddy Co., NM **GL**: 3,559' **ZERO**: 15' **KB**: 3,574' **CASING PROGRAM** SPUD DATE: 02/17/77 COMPLETION DATE: 04/05/77 **COMMENTS**: API No.: 30-015-22053 13-3/8" 64# H-40. 356' NSL Order # 5377 2-22-77 8-5/8" 24# J-55 1,150' Perf at 406 Surface 105 sx plug 17-1/2" Hole 4.5" 11.6# K-55 729' from 0' to 406' To form the 4.5" 10.5# K-55 5,890' casing shoe 4.5" 11.6# K-55 1,899' 8,518' plug and the **Bottom Hole** surface plug. 13-3/8" @ 356" After 12-1/4" Hole w\ 380 sx (Circ.) WOR DTAF Perf at 1.200' TOPS 60 sx plug from 1,000' to 1,200' 695' SA Across casing shoe Glorieta 2,123' 8-5/8* @ 1,150 Abo 4,0801 w/ 800 sx (Circ.) Wolfcamp 5.237 Canyon 7,350 WOCLTAR Perf at 2,173' Strawn 7.628 60 sx plug from 1,973' to 2,173' Atoka 8,141' 7-7/8" Hole Across Glorieta top Morrow 8,262 Perf at 4,130' WOC + 7NE 8,508' Chester 60 sx plug from 3,930' to 4,130' Across Abo top word the Perf at 5,287' 60 sx plug from 5,087 to 5,287 Across WC top TOC @.6;100' CIBP @ 6,568 w\ 40 sx plug from EWOE YHAS JAKE 6,040' to 6,568' over WC perfs & acorss cmt top Wolfcamp Perfs: 6,618'-6,674' (120) 180 F2 - 1 25 sx plug from 7,100 to 7,400 Across Canyon top 25 sx plug from 8,012' to 8,312' Across Morrow top 4-1/2"" @ 8,518' Not to Scale w\ 675 sx 07/20/16 FC: 8,485' JMH. TD: 8.560'

CONDITIONS FOR PLUGGING AND ABANDONMENT

District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.

- A notice of intent to plug and abandon a wellbore is required to be approved before plugging
 operations are conducted. A cement evaluation tool is required in order to ensure isolation of
 producing formations, protection of water and correlative rights. A cement bond log or other
 accepted cement evaluation tool is to be provided to the division for evaluation if one has not
 been previously run or if the well did not have cement circulated to surface during the original
 casing cementing job or subsequent cementing jobs.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 7. Produced water will not be used during any part of the plugging operation.
- 8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 9. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 10. Class 'C' cement will be used above 7500 feet.
- 11. Class 'H' cement will be used below 7500 feet.
- 12. A cement plug is required to be set 50' above and 50' below, all casing shoes, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 13. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 14. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 15. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 16. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

- 17. Formations to be isolated with cement plugs are:
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 18. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and well number
- 3. API number
- 4. Unit letter
- 5. Quarter section (feet from North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging date
- 8. County

(SPECIAL CASES)

AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)