Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED)
OMB NO. 1004-013	5
Expires: July 31, 201	(

SUNDRY Do not use thi abandoned wel	Lease Serial No. NMNM13996 If Indian, Allottee or Tribe Name						
SUBMIT IN TRII	7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well					8. Well Name and No.		
☑ Oil Well ☐ Gas Well ☐ Other					CEDAR CANYON 22 FEDERAL COM 6H		
Name of Operator Contact: DAVID STEWART OXY USA INC. E-Mail: david_stewart@oxy.com					9. API Well No. 30-015-43759		
3a. Address P.O. BOX 50250 MIDLAND, TX 79710	(include area code 5-5717)	10. Field and Pool, or Exploratory CORRAL DRAW BONE SPRING				
4. Location of Well (Footage, Sec., T.	11. County or Parish, and State						
Sec 22 T24S R29E SWSW 1060FSL 207FWL 32.198466 N Lat, 103.979724 W Lon					EDDY COUNTY, NM		
12. CHECK APPR	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, RE	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	☐ Acidize	☐ Deep	oen .	☐ Producti	on (Start/Resume)	. Water Shu	ıt-Off
_	☐ Alter Casing	☐ Frac	ture Treat	☐ Reclama	ation	☐ Well Integ	grity
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	□ Recomp	lete	Other	
☐ Final Abandonment Notice	☐ Change Plans	🛛 Plug	and Abandon	n Temporarily Abandon			
☐ Convert to In		tion Plug Back Water			risposal		
13. Describe Proposed or Completed Ope If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi OXY USA Inc. respectfully req	illy or recomplete horizontally, and the performed or provide operations. If the operation result is and onment Notices shall be file that inspection.) The performance of the performa	give subsurface the Bond No. on ults in a multiple d only after all r	locations and measi file with BLM/BIA completion or rec equirements, include	ared and true ver A. Required sub completion in a n ling reclamation	rtical depths of all pertir sequent reports shall be ew interval, a Form 316 i, have been completed,	ent markers and z filed within 30 da 0-4 shall be filed	zones. ays once
the hole. See attached for the 1. PU 1000' of 2-7/8" 6.5# tbg 2. Establish circulation at 170 3. Pump cement job at agreed time (70 Bc) is three hours. 4. Under displace cement to le (250' cement above final TOC. 5. Trip out of hole at no more to Start with 3 bpm and increase of plug.	and stinger, trip in hole to gpm (cement rate). d upon volumes (plug #1). eave 4-5 BBLs of cement ; ~85 psi overbalanced). han 45'/min to 500' above	Estimated (principle the planned	TOC. Stage up	pumps slow	ıly.	,	:
14. I hereby certify that the foregoing is	Electronic Submission #3		l by the BLM We ent to the Carlsi		System		
Name (Printed/Typed) DAVID STEWART			Title SR. REGULATORY ADVISOR				
					تناسب	. \	
Signature (Electronic S	ubmission)	,	Date 09/08/2	016	arovals will	'	
	THIS SPACE FO	R FEDERA	L OR STA	ending BLN	A approvals will ly be reviewed		,
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the		Title Office	subsequent and scanne	A approvais to Lly be reviewed ed	Sale	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #350524 that would not fit on the form

32. Additional remarks, continued

6. Drop wiper ball

Circulate 3x bottoms up at 300 gpm. (Increased from 170 gpm to 300).

8. Pick up used 9.875" roller cone bit with bit sub and drill pipe.9. Trip in hole to 500' above plug.

- 10. Wait on cement; 7 hours total from finishing pumping.
 11. Trip in hole, washing at 300 gpm (100'/min annular velocity).
 12. If no cement is encountered within the top 200'of the top of plug estimate, discuss with FDS, DS and DE.
- 13. If any cement returns are observed, stop, trip back out to 500' above plug, circulate clean, discuss with FDS, DS, and DE

discuss with FDS, DS, and DE

14. Tag each cement plug with 15,000 lb.

15. Trip out of hole with roller cone and drill pipe.

16. Repeat steps 1-15 for plugs 2-5

a. Start subsequent plugs at tag depth and callout for additional Class C Neat as needed.

b. Note that plug #5 has 2% Calcium Chloride and is meant to be the last plug

c. Plug #5 70 Bc: 3 hrs 26 minutes

d. 500 psi compressive strength: 5 hours 39 minutes

17. Pull out of hole

17. Pull out of hole

- 18. Wait on cement 7 hours (~500 psi compressive strength) while conducting SIMOPS in preparation to skid the rig.
- 19. Prepare to skid to the Cedar Canyon 22 Federal Com 5H

All cement plugs must be tagged.