

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-005-60949

Release Notification and Corrective Action

NMLB 0608137717

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Fairview Production Co. dba Morris A Richardson	Contact John Elliott	
Address PO Box 1995 Muldrow, OK 74948	Telephone No. 918-261-6700	
Facility Name Tamarack	Facility Type Tank Battery	
Surface Owner	Mineral Owner	Lease No. LG-03591

LOCATION OF RELEASE

Unit Letter D	Section 32	Township 06S	Range 26E	Feet from the 1650'	North/South Line North	Feet from the 330'	East/West Line West	County Chaves
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 4 bbls	Volume Recovered 4 bbls
Source of Release water tank overflow	Date and Hour of Occurrence 11/29/05 evening	Date and Hour of Discovery 11/30/05 morning
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Batchelor (on site)	
By Whom? STAN THOMPSON	Date and Hour 10:00 AM 11/30/05	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
DEC 5 2005
OCCUPANCY

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A backhoe digging in the area inadvertently cut underground wires supplying our transfer pump. Subsequently, the pump did not switch on and the tank overflowed onto the ground.

Describe Area Affected and Cleanup Action Taken.*

The affected area was limited to the immediate area around the water tank. A pump truck was brought on location and sucked up the free standing liquid. The stained soil will be scraped up and hauled off premises to an authorized disposal site. A second water tank is being brought in and connected to the existing water tank to provide additional storage space. This will allow more than 24 hours protection from future spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: John S Elliott

Approved by District Supervisor:

Title: Member

Approval Date:

Expiration Date:

E-mail Address: pohi82@yahoo.com

Conditions of Approval:

Accepted for record
NMOCD

Attached ☐

Date: 11/15/05 Phone: 918-261-6700

* Attach Additional Sheets If Necessary